

Book 2012 Page 1967 Type 43 001 Pages 8 Date 7/05/2012 Time 10:31 AM

Rec Amt \$.00

INDX **ANNO SCAN**

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

TRANSFEROR:

Name

Debra J. Brant

Address

1108 Rittenhouse Street, Des Moines, IA 50315

Number and Street or RR

City, Town or P.O.

State

Zip

TRANSFEREE:

Name

Ivan G. Ludwig

Address

7392 Lapwai Road, Lewiston, IN 83501

State

Zip

Address of Property Transferred:

2924 St. Charles Rd., St. Charles, IA 50240 Number and Street or RR City, Town, or P.O. St

Zip

Legal Description of Property: (Attach if necessary)

Parcel "E", located in the Northwest Quarter (1/4) of the Southwest Quarter (1/4) of Section Seventeen (17), Township Seventy-five (75) North, Range Twenty-six (26) West of the 5th P.M., Madison County, Iowa, as shown in Plat of Survey filed in Book 2, Page 468 on May 12, 1994 in the Office of the Recorder of Madison County, Iowa.

~	There a	are no	known	wells	situated	on this	propert	V.

There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)

There is no known solid waste disposal site on this property.

__ There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

✓ There is no known hazardous waste on this property.

__ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

✓ There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks.)
in instructions.)
There is an underground storage tank on this property. The type(s), size(s) and any knowr
substance(s) contained are listed below or on an attached separate sheet, as necessary.
5. Private Burial Site (check one)
✓ There are no known private burial sites on this property.
There is a private burial site on this property. The location(s) of the site(s) and known
identifying information of the decedent(s) is stated below or on an attached separate sheet, as
necessary.
6. Private Sewage Disposal System (check one)
All buildings on this property are served by a public or semi-public sewage disposal system.
This transaction does not involve the transfer of any building which has or is required by lave to have a sewage disposal system.
There is a building served by private sewage disposal system on this property or a building
without any lawful sewage disposal system. A certified inspector's report is attached which
documents the condition of the private sewage disposal system and whether any
modifications are required to conform to standards adopted by the Department of Natura
Resources. A certified inspection report must be accompanied by this form when recording.
There is a building served by private sewage disposal system on this property. Weather o
other temporary physical conditions prevent the certified inspection of the private sewage
disposal system from being conducted. The buyer has executed a binding acknowledgmen
with the county board of health to conduct a certified inspection of the private sewage
disposal system at the earliest practicable time and to be responsible for any require
modifications to the private sewage disposal system as identified by the certified inspection
A copy of the binding acknowledgment is attached to this form.
There is a building served by private sewage disposal system on this property. The buyer ha
executed a binding acknowledgment with the county board of health to install a new private
sewage disposal system on this property within an agreed upon time period. A copy of the
binding acknowledgment is provided with this form.
There is a building served by private sewage disposal system on this property. The building
to which the sewage disposal system is connected will be demolished without being
occupied. The buyer has executed a binding acknowledgment with the county board of health
to demolish the building within an agreed upon time period. A copy of the binding
acknowledgment is provided with this form. [Exemption #9]
This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption: [Note: for exemption #9 use prior check box]
The private sewage disposal system has been installed within the past two years pursuant to
permit number
DOMINI TRAINED.
Information required by statements checked above should be provided here or on separate
sheets attached hereto:
I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND
THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
THE THE THE STATE OF THE PARTY OF THE STATE
\mathcal{O} . \mathcal{O}
Signature: Deletin (312) Telephone No.: (5/5) 577-72/2
(Transferor or Agent)



Time of Transfer Inspection Worksheet.

Other components:
• •
Alarms Working? disinfection working?
Control box inspection posts
Other components
Overall condition of the private sewage disposal system.
Report system status
Explain (attach additional pages as needed):
Comments LATERAL FIGUR Wet Sign of Part Su-facing
CASSELL GIRLA COLL COLLARS CONTRACT
Comments: Cristal City of July 2017
Not Serfacing day of inspedier
$oldsymbol{arphi}$
Site status at conclusion of Time of Transfer inspection:
Verify that controls are set on the appropriate mode.
Power is on to all components.
Revisit all components to verify lids are secure.
• Gather all tools for reproval from the site.
 Verify that no sewage is on the ground surface.
Using this worksheet, wate a manutive report of the inspersion needle and much a site sketch.
This report indicates the condition of the private sawage disposal system at the time of
the inspection. It does not guarantee that it will continue to function satisfactorily.
Signature of Certified inspector 7/7 Date 5-30-12
Signaluse of Certified inspector
Name (print): LARRA (HOMAS) Certificate & 820 9
Address 5731 SE 68 Am DIM TA
Phone # 5/5-267-5477
Provide a copy of this report, the name ive report and sheach to the sellen/agent, hoperingent, the
county suctuitant environmental health office in the county the inspection was conducted and to;
Iowa DNR Onsite Wastewater Program
502 B. 9th St.
Des Moines, IA 50319
the state of the s
$\cap \cap \cap$
$\bigcup V$
3-2000
· A MANAGE



Time of Transfer Imperior Report (DINK Form 542-0191)

Property infragration	•
COMMENTED DEBRA BLANT	
CORRESPONDED TO TOTAL TOTAL TOTAL	
Sayer	
	Besitor
- ST A44 2024 Ca a	DALES Rd STCHOLLED, FO MADISON CO
THE PROPERTY DESIGNATION OF THE PROPERTY OF TH	ALLES DI OCI
Legal Learningion	THACLE, TO MADISON C
No methods 2	
No of bedrooms 3 Last occupied? C	vedent Bonne
Pennishan data UNICAN Sepa	THE PERSON OF LAND
Sopra	Control of the state of the sta
Soule switch information	OEL BOY OF IR.
THE PERSON NAMED IN COLUMN	
Septic tooklet size 1250 3.40 Extra	<u>^</u>
Test promped yes	to Concrete continue 3000
Septiches supported that the San 12	Install proper (Homes Bra
Sale and the sale and the sale and	Commer Rea
Tank prospects date	licenses principal
According to the state of the s	THE PARTY OF THE P
	Exerci passper
Condition Contract?	
	Service provides
Prince tender type size	
die die	
Distribution system: distribution box Poly History pipe(s)	COMMISSION
The state of the s	Springer 4
Honder pipe(s)	# of lines 4 Pressure desert No
Garage and the second s	Fromsome dosered NO
Entitle of stronger and the Control	-
length of absorption to the 400 fa.	P. Jane
to a firm of the control of the cont	· demonstry Record Tape
type of trench instantal Ortakilds	determinately Hydradia LOAD
Size of send filter	
The view of the same of the sa	disconnect by
	PROPERTY AND ADDRESS OF THE PROPERTY ADDRESS OF THE PROPERTY AND ADDRESS OF THE PROPERTY ADDRESS OF THE PROPERTY AND ADDRESS OF THE PROPERTY ADDRESS OF THE PR
,	Desily
Media filter type	
Condition the Condition desc	service profession
OPDES General Permit No. de annual an A (e)	
NFDES General Permit No. 4: negrines NO	panish NOI provided
	The second secon
	Δ ·
<i>[] []</i>	\$43.00m
. 1//	X/
\ V/4 A	
$\mathcal{M}\mathcal{N}$ ()	
05/30/12 01:00 PM	· Bear 4
1 - 1 - 1 - 1 - 1	Page 4

MG to: to 21/05/80

\$ 2924 St Charles Rd. formit # 1779 ZHI LINKO HOSTOVII 90°21 ZZ-50-210;Z 05/29/12 11:23 AM

LOL

Kenhart Construction

Kephart Contraction 310 West Clanton Street St. Charles, In. 50240

June 14, 2012

I was contacted by Remax Renovators from Indianola on 6/11/12 to check on a previous Time of Transfer inspection. It had a discrepency on what had been observed by another contractor. Property located at 2924 St charles Road in Madison County.

I was faxed a copy of a time of transfer report. It stated the absortion field was very wet. He has loaded the system for 10 min. and said the effluent would follow up through the probe holes through the surface of the ground and puddle.Report stopped, based on poor results. This report was done on 5/30/12.

I inspected the site on 6/13/12 and observed the lateral field had very healthy vegetation over the 1,3, & 4 laterals. Which tells me lateral 2 is not receiving any effluent. It showed no signs of effluent being on the surface and no odor. I exposed the distribution box, found the levelers on 2 were turned to where they would not receive any effluent. I releveled all levelers in the distribution box. I loaded the field with 150 gallons of water. Observed by the rural water meter pit , for 45 min. I did not observe any water ponding or surfacing. I probed for 1 hour and did not see any water making it to the surface in any probe holes.

As of this date 6/13/12 I don't see a problem with this system. Except the dog run needs to be moved off the lateral field

Clint Kephart

Certified Inspector

NEHA Certified Installer

Kephart Construction 515-210-5677

The findings in this report are not any guarantee of the future performance of this system. the findings are based on observations of the system at the time and day of the inspection only. Kephart Const.will not be held liable for any hidden or unforseen damages to this system. The ibspection has been performed in accordance with the guidelines set forth by the Iowa DNR and in compliance with

IAC567-chapter 69. All septic systems require regular maintennance and eventually require repairs.

Y&Z.

Thomas Bros. Septic Service

5731 SE 6th Âve Des Moines, IA 50327

Proudly morning central Jean ever of yours

05/30/12

Inspection report for the property located at 2924 St. Charles Rd in Madison county. I have uncovered, inspected and pumped this system. I found a dual compartment concrete septic tank in good condition. Just a very slight amount of decay around the outlet pipe. Based on the approximate age of the system I feel the decay is minimal. The distribution box was located and uncovered. I loaded the system with a water hose for around 10 minutes and began noticing a very wet absorption field. All laterals were very wet even at the ends of the field lines. Effluent would follow the probe hole to the surface of the ground. Normally I will load this system for 30 to 40 minutes. I stopped after 10 minutes based on the poor results.

I also noticed that the first 10 feet or so of the upper most lateral is under a outside shed. Also located midway through the same lateral is a burn pit directly over the lateral. These laterals are plastic and very shallow.

Larry Thomas
Certified Inspector
NEHA Certified Installer

Thomas Bros. Septic 515-681-1478

The findings in this report are not my guarantee of the future performance of this system. The findings are based on observations of the system at the time and day of the inspection only. Thomas Bros. will not be held liable for any hidden or unforeseen damages to this septic system. The inspection has been performed in accordance with the guidelines set forth by the lowa DNR and in compliance with IAC567-chapter 69. All septic systems require regular maintenance and eventually require repairs.

SAL