UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF


Land Survey Monuments situated in Section 29, Township 88, Range 4, of the Fifth Principal Meridian, DELAWARE County, Iowa.
Previously recorded in Book _____, Page _____.


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: NW Cor. – Found 1/2"ø Rebar w/cap #8419 IN open field 1.0' Deep as per county tie sheet.
W1/4 Cor. – Found 2"ø x 2.5' Long open pipe w/nail & flaggins in top; top 0.9' of pipe bent SWly, straightened & set 1/2"ø rebar in center.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)





I hereby certify that this plat, map, survey or report was made by me or under my direct personal supervision and that I am a duly Registered Land Surveyor under the laws of the State of Iowa.

Paul H. Helland Date 12/15/95

PAUL H. HELLAND, P. E. & R. L. S. IOWA REGISTRATION NO. 6505
My registration expires December 31, 1995

HELLAND ENGINEERING & SURVEYING, LTD.
Thunder Ridge Bank Building
2322 West First St., Suite B
Cedar Falls, Iowa 50613
319-266-0161

List Corners to be Indexed

Corners	Section	Twp	Range
NW	29	88	4
W1/4	29	88	4

FILE No. 184-1829
RECORDING FEE $ 6.00
TRANSFER FEE $ _____

FILED FOR RECORD THE 2 DAY OF January, 1996 AT 10:15 O'CLOCK A M. BOOK 1 PAGE 322

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
Cor. Mon.