COMPUTER RECORDED COMPARED

FILED NO. 3242

BOOK 45 PAGE 557

99 FEB - 8 PM 2: 47

AUD S

MANSON TECHNICATION TO THE CORDER MANSON TO THE CORDER TO

Prepared By: J. Brian Morrissey, P.E. & L.S., 1926 Pammel Park Road, Winterset, Iowa 50273-8317, Telephone: (\$15) 462-2166 HTY. 10W

AFFIDAVIT

STATE OF IOWA)
) SS
COUNTY OF MADISON)

I, J. Brian Morrissey, being first duly sworn upon oath depose and state that I am a land surveyor duly licensed in the State of Iowa, and that the Plat of Survey for Wilson Young and Richard Ray, located in the Southwest Quater of the Northwest Quarter of Section 18, Township 76 North, Range 28 West of the Fifth Principal Meridian, Madison County, Iowa, was prepared by me or under my direct personal supervision.

I further depose and state that it has came to my attention that there is an error on said Plat filed the 26th day of January, 1999, in Farm Plat Book 3, Page 381, at the Madison County, Iowa, Recorder's Office.

The error is that the Plat indicates that there was a 5/8" rebar, with cap P.L.S. 7995, set at the northwest highway right of way corner. Due to a leaning corner post, the capped rebar was not set and a P-K nail was set 0.20 north of the right of way corner in the top of said corner post.

The Madison County, Iowa Recorder is requested to place a notation on the original plat showing the date of filing and Book and Page of recording this Affidavit in compliance with Section 354.24, Code of Iowa.

J. Brian Morrissey, P.E. & L.S. lowa License No. 7995

Subscribed and Sworn to before me by the said J. Brian Morrissey, this 5th day of February,

MICHAEL IAMES HACKETT
MY COMMISSION EXPIRES

1999.

Notary Public in and for the State of Iowa