

Document 2014 GW1045

Book 2014 Page 1045 Type 43 001 Pages 8 Date 5/02/2014 Time 3:15 PM Rec Amt \$.00

INDX ANNO SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENTTO BE COMPLETED BY TRANSFEROR

TRAN	ISFEROR:			
Name	Justin E. Goodlaxson			
Addre	Number and Street or RR	Winterset City, Town or P.O.	IA State	50273-8223 Zip
TRAN	ISFEREE:			
Name	Troy Kerr			
مدادات	00 1000 054h Ct CW	Fuorett	١٨/٨	08204
Addre	Number and Street or RR	Everett City, Town or P.O.	WA State	98204 Zip
۸ ما ما م	as of Duan subv. Turn of supply			
	ss of Property Transferred:	Winterset	1.0	50273
2200	Holliwell Valley Ct Number and Street or RR	City, Town or P.O.	IA State	Zip
	(ells (check one)There are no known wells situated of the there is a well or wells situated on the theory or set forth on an attached separate	his property. The type(s), locati	on(s) and legal statu	ıs are stated below
2. S	olid Waste Disposal (check one)	emosi, as mossocary.		
Ø		sal site on this property.		
yk B	There is a solid waste disposal s Attachment #1, attached to this docu		mation related ther	eto is provided in
3. H	azardous Wastes (check one)			
K	There is no known hazardous waste	on this property.		
	There is hazardous waste on this p attached to this document.	roperty and information related	thereto is provided	in Attachment #1,
4. U	nderground Storage Tanks (check o	ne)		
Z	There are no known underground s and residential motor fuel tanks, mos			
	There is an underground storage tall contained are listed below or on an a			nown substance(s)

5.	Pri	vate Burial Site (check one)
	区	There are no known private burial sites on this property.
		There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.
6.	Pri	vate Sewage Disposal System (check one)
	· !	All buildings on this property are served by a public or semi-public sewage disposal system.
		This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
	×.	There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
		There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
		There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
		There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
		This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]:
		The private sewage disposal system has been installed within the past two years pursuant to permit number
		ation required by statements checked above should be provided here or on separate sheets ed hereto:
Sigr	natu	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM FORM THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT. Te: The image of the instructions for this form the instructions for the instruction in

GROUNDWATER HAZARD STATEMENT

ATTACHMENT #1

NOTICE OF WASTE DISPOSAL SITE

a.	So	lid Waste Disposal (check one)
		There is a solid waste disposal site on this property, but no notice has been received from the Department of Natural Resources that the site is deemed to be potentially hazardous.
		There is a solid waste disposal site on this property which has been deemed to be potentially hazardous by the Department of Natural Resources. The location(s) of the site(s) is stated below or on an attached separate sheet, as necessary.
b.	Ha	zardous Wastes (check one)
		There is hazardous waste on this property and it is being managed in accordance with Department of Natural Resources rules.
		There is hazardous waste on this property and the appropriate response or remediation actions, or the need therefore, have not yet been determined.
Fu	ther	descriptive information:
	-	
		I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS
		∧ , \ FORM
		AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
Sig	natu	re: XIVA (STelephone No.: (SIV) 313-1183
		(Translation of Agent)

FILE WITH RECORDER

DNR form 542-0960 (July 18, 2012)



Time of Transfer Inspection Report

Alarms Working?	disinfection ne worki	ing?
Control box ne Timers se	inspection ports	
Other components		
Overall condition of the private sewage disposal system	<u>m</u>	
Report system status		
Explain (attach additional pages as needed):		
Comments: Pemp Septic Look ruery 3 do 5	years, Very Topodart.	1
- clean affluent filler at least once any	cas.	
Site status at conclusion of Time of Transfer inspectio Verify that controls are set on the appro Power is on to all components. Revisit all components to verify lids are Gather all tools for removal from the si Verify that no sewage is on the ground	opriate mode. e secure. ite.	
Using this worksheet, write a narrative report of the in	ispection results and attach a site	e sketch.
This report indicates the condition of the private sews the inspection. It does not guarantee that it will conti	nue to function satisfactorily.	
Signature of Certified inspector: Value Canada Name (print): Vance Scotts Address: 500 west than Storet St. Charles Phone # 1941: 3342, 2440	Certificate	#: 849 a
Provide a copy of this report, the narrative report and county sanitarian/environmental health office, county conducted and to;	sketch to the seller/agent, buyer Recorder in the county the insp	lagent, the section was
Iowa DNR Onsite Wastewater Program 502 E. 9 th St. Des Moines, IA 50319		

542-0191

6-2009



Time of Transfer Inspection Report (DNR Form 542-0191)

Property information
Current owner Justin and Kathy Goodlaxson Buyer Realtor Sallie madden 577-2475 Mailing address 2206 Hallwell Calley Court Walers To 50273
Buyer Realtor Sellie modden 577.2475
Mailing address adole Hallwell Calley court wasterset To 50273
·
Site Address/County 3200 Holling Walley Court Madison County
Legal Description Lot 2
No. of bedrooms 3 Last occupied? Records available
Permit/installation date Separation distances (R) no?
064.04
Septic system information
Septic tank(s): size 1,500 galles material concerles condition seedlest
Tank numbed?
Septic/trash/processing tank: size material condition
Tank pumped? date licensed pumper
Aerobic treatment unit (ATU) mfgr size
Tank pumped? date licensed pumper
Maintenance contract? expiration date service provider
Condition
Pump tanks/vaults: type size condition
Pump tanks/values: type size condition
Distribution system: distribution box es outlets used condition
Header pipe(s) / # of lines 4 Pressure dosed?
Ticades pipe(s) ii of miss i resource deserving
Secondary treatment:
length of absorption fields 4x 100 = 400 Sech determined by
condition of fields determined by Ville
type of trench material broke Caseas
Type of transfer and the state of the state
Size of sand filter determined by
Vent pipes above grade? discharge pipe located?
Effluent sample taken? Results
Media filters: type
Media filters: type expiration date service provider
Condition
NPDES General Permit No. 4: required? permitted? NOI provided
f
542-0191

ANYTHME SEPTIC SERVICES II VANCE SMITH ST. CHARLES, IA 50240 641-396-2440

REAL ESTATE SEPTIC INSPECTION

On March 23rd, 2014, Anytime Septic Services II did Time of Transfer Real Estate Inspection on distribution box, septic tank, and lateral field at 2206 Holliwell Valley court, lot#2, Winterset, Iowa 50273 Justin and Kathy Goodlaxson residence. The septic tank is a 1,500 gallon two compartment concrete tank that is 12 inches below ground surface with 2 sections of 6 inch by 22 inch in diameter plastic Poly Lok risers with 22 inch screwed down plastic Poly Lok lids at ground surface, above the tee baffles on both inlet and outlet ends of tank. On the outlet side of septic tank there is a 4 inch squared Poly Lok effluent filter inserted into a 4 inch squared shaped baffle that is Very Important to clean at least once or maybe even twice a year., by simply lifting filter straight up from squared shaped baffle and hosing clean with garden hose than reinserting into place. The distribution box is a plastic Tuff Tite box with 4 inch diameter tee baffle inside box. Distribution box is 8 inches below ground surface with a supporting concrete surrounding. Distribution box has 4 lines leaving box through 4 speed levelers equally distributing effluence's into 4-24 inch plastic biodefuser chambers that are 100 feet each totaling 400 feet of laterals 12 inches below ground surface. The absorption field shows no evidence of any ponding or surfacing of effluence's at ground surface. On the South side of house is a clean out port from house to septic tank. Appears schedule 40 pipe was used through out complete septic system and is functioning properly.


ANYTIME SEPTIC SERVICES II IS NOT RESPOSIBLE FOR ANY FAILED SEPTIC SYSTEMS.

PAGE 05/06

VALIMESEPTICSVCSIIP

01/03/5000 10:43 16413062440

Permit # 064-04 Lot 2 Holliwell 10/1/04 2206 Holliwell Valley Ct.



No Pictures

Anytime Septic Services II 502 W. Main St,. Saint Charles, Iowa 50240								
		OADER NO		DEPARTMENT		DA		
NA	<u>≅.€</u>	· • • •	2475	515-8	34-247	5	3.24	44
		5. z.L.	n + Ko	Hhy G	eedla	CSON		
ADI	ノドヒング			•				
CIT	T, SIRIC. L	۳	Holling		•	ra bath		
<u>\</u>	L	وإبهلو	CASH	4 502	13			
	SOLO	BY	CASH	£.0,D,	CHARGE	ON: ACCT.	MDSE, ÁE	TO. PAID OUT
پر	UANTITY	7		e AnimaloN	<u>L</u>	1	RICE	ABBOULET
H	DAMILLI		<u> </u>	SCRIPTION			HIPE	AMOUNT
	·	}		~				
2		3.35	3.14 Da	mpada	a cla		,500 b	- حمالت
2		Sec	achon	معلم	cleane	a deci	ed I	Mar
4.		<i>i</i> , ,	22 40	•		- 1	f	
5		.1	Feeline	•		1 .		
6		4]			•	1.	•	i
7		-	1, die	P.+ C	126		a vedy	
8		†		· · · · · · · · · · · · · · · · · · ·			,,,	-
9	<u></u>	}			-\$-\\$. (- 47 \	000
H	· · · · · · · · · · · · · · · · · · ·							
10			- '\\	ask y	UE		<u> :</u>	
"	·	4	· · ·	, , , , , , , , , , , , , , , , , , , 				
12	·		/	Tare	M			
13			1/1	of the same			ľ	
14				**************************************	·····			
15		,	······································					 -
16		 			,	 		-
\vdash		 						
17	•	 					;- }	
18	EEVED BY				That		4	50 6
:NE	PETAKTI-QA							
١.								