DELAWARE COUNTY IOWA
FILED
2003 JN 25 AM 10: 02
BOOK 2003 PAGE 2994
DEBORAH L. PEYTON
DELAWARE CO. RECORDER
6.00

Prepared by: SCHNEIDER Land Surveying and Planning, Inc. P.O. Box 105 Peosta, Iowa 52068 563-556-9055

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 26, Township 89 North, Range 6 West of the Fifth Principal Meridian, Delaware County, Iowa.


Previously recorded SW CORNER - BOOK 2, PAGE 28 .
(BOOK, PAGE / INST. NO. / CABINET, SLIDE)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: A 1/2" REBAR WITH A DAMAGED CAP WAS FOUND AT THE SW CORNER OF SECTION 26 AS ILLUSTRATED IN SECTION CORNER CERTIFICATE FILED IN BOOK 2, PAGE 28. THE CORNER WAS RETIED DUE TO REMOVAL OF THE FENCE. THE 1/2" REBAR WAS TIED AND USED AS THE CORNER.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

David P. Schneider 6/20/2003

David P. Schneider P.L.S. #14417 Date:
My license renewal date is December 31, 2003.

Pages or sheets covered by this seal: THIS SHEET ONLY

SCHNEIDER
Land Surveying & Planning, Inc.
P.O. Box 105 Peosta, Iowa 52068
Ph. #563-556-9055 Fax#563-556-9054

LICENSED LAND SURVEYOR
DAVID P. SCHNEIDER
#14417
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
SW	26	89N	6W

JOB NO. 225A

BOOK 2003 PAGE 2994