Book 2009 Page 4274
Document 2009 GWH-4274 Type 53 001 Pages 6
Date 11/16/2009 Time 9:03:09AM
Rec Amt $.00

DEBORAH L PEYTON, RECORDER/REGISTRAR
DELAWARE COUNTY IOWA

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT
TO BE COMPLETED BY TRANSFEROR

TRANSFEROR:
Name Olive Ann Francois and Robert J. Francois

Address 504 E Butler Street, Manchester, Iowa 52057
Number and Street or RR | City, Town or P.O. | State | Zip

TRANSFEREE:
Name Trent L. Jared and Jessica D. Korte

Address 493 Main Street, Arlington, Iowa 50606
Number and Street or RR | City, Town or P.O. | State | Zip

Address of Property Transferred:
1895 120th Avenue, Manchester, Iowa 52057
Number and Street or RR | City, Town, or P.O. | State | Zip

Legal Description of Property: (Attach if necessary) Parcel C in the Southeast ¼ of Section 17, Township 89 North, Range 6 West of the 5th Principal Meridian, Delaware County, Iowa, according to plat recorded in Book 2009, Page 3980.

1. **Wells (check one)**
   - ☐ There are no known wells situated on this property.
   - ☑ There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.
2. **Solid Waste Disposal (check one)**
   - ☑ There is no known solid waste disposal site on this property.
   - ☐ There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.
3. **Hazardous Wastes (check one)**
   - ☑ There is no known hazardous waste on this property.
   - ☐ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.
4. **Underground Storage Tanks (check one)**
   - ☑ There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
   - ☐ There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. **Private Burial Site (check one)**
   - ☑ There are no known private burial sites on this property.
   - ☐ There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.
6. **Private Sewage Disposal System (check one)**
   - ☐ There are no known private sewage disposal systems on this property.
   - ☑ There is a private sewage disposal system on this property. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
   - ☐ There is a private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form. When the inspection is completed, an amended Groundwater Hazard Statement shall be recorded with the certified inspection and shall include the document numbers of both the real estate transfer document and the original Groundwater Hazard Statement.
   - ☐ There is a private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
   - ☐ This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption: _____.
   - ☐ The private sewage disposal system has been installed within the past two years pursuant to permit number _____.

Information required by statements checked above should be provided here or on separate sheets attached hereto:

#1 The well is A drilled well located 75 ft west of house and it is A active well

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM
AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.

Signature: Eline Ann Francois (Transferor or Agent) Telephone No.: (563) 927-4043

Time of Transfer Inspection Report

Other components:
Alarms _____ Working? _____ disinfection _____ working? _____

Control box _____ Timers_____ inspection ports _____

Other components _____

Overall condition of the private sewage disposal system

Report system status All working good

Explain (attach additional pages as needed): _____

Comments: _____

Site status at conclusion of Time of Transfer inspection:

- Verify that controls are set on the appropriate mode.
- Power is on to all components.
- Revisit all components to verify lids are secure.
- Gather all tools for removal from the site.
- Verify that no sewage is on the ground surface.

Using this worksheet, write a narrative report of the inspection results and attach a site sketch.

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified inspector: Robb Harter Date: 10-1-09
Name (print): Robb HARTER Certificate #: _____
Address: 3071 160 St Dyersville
Phone # 563-542-1010

Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent, the county sanitarian/environmental health office, county Recorder in the county the inspection was conducted and to;

Iowa DNR Onsite Wastewater Program
502 E. 9th St.
Des Moines, IA 50319

Time of Transfer Inspection Report (DNR Form 542-0191)

Property information

Current owner FRANCOIS Olive Bob
Buyer _____ Realtor BRIAN FRANCOIS
Mailing address 1895 120 TH AVE MANCHESTER 52057

Site Address/County 1895 120 TH AVE MANCHESTER 52057
Legal Description COFFING GROVE Section 17

No. of bedrooms 3 Last occupied? 6 MONTH Records available no

Permit/installation date _____ Separation distances ok/ no? ok

Septic system information

Septic tank(s): size 1250 GAL material _____ condition good
Tank pumped? Yes date 10-1-09 licensed pumper _____
Septic/trash/processing tank: size 1250 material _____ condition _____
Tank pumped? 10-1-07 date _____ licensed pumper ST

Aerobic treatment unit (ATU) mfgr _____ size _____
Tank pumped? _____ date _____ licensed pumper _____
Maintenance contract? _____ expiration date _____ service provider _____
Condition _____

Pump tanks/vaults: type _____ size _____ condition _____

Distribution system: distribution box yes outlets used 3 condition good
Header pipe(s) _____ # of lines _____ Pressure dosed? _____

Secondary treatment:
length of absorption fields _____ determined by _____
condition of fields _____ determined by _____
type of trench material _____

Size of sand filter _____ determined by _____
Vent pipes above grade? _____ discharge pipe located? _____
Effluent sample taken? _____ Results _____

Media filters: type _____
Maintenance contract? _____ expiration date _____ service provider _____
Condition _____

NPDES General Permit No. 4: required? _____ permitted? _____ NOI provided _____

Harter Custom Pumping, Inc & Septic Service

Robb Harter * Owner/ Operator
3031 160th Street Dyersville, IA 52040 * 563-875-8730 or 563-542-1010

****

Homeowners: Olive Francois
1895 120th Ave
Manchester
IA 52057

Age of Property 2002
Occupied
Yes or No

Inspection Co: Harter Septic
3031 160 St Dyersville 52040
Date of Inspection: 10-1-09

Does this evaluation/inspection meet the requirements of state and local agencies? Yes X No ___ N/A ___

Section 1:

Location of the system: East West (North) South
Was Water run into the system for 30 minutes? (Yes) No
Does the septic tank have a visible riser? (Yes) No
Estimated size of tank 1250 Gallons *Basis for estimate*
What is the separation between well and septic? 120 Ft
Does the separation of the well and septic meet local requirements? (Yes) No N/A

Section2: Disposal Field

Any evidence of malfunction (No) Yes (Please check all applicable observed conditions)
___ Wet Areas ___ Unusual green/lush vegetation
___ Liquid Discharges to surface ___ Discharge pipe of unknown origin
___ Localized surface settling ___ Other (Describe below)


Septic Tank:

Septic tank material X Concrete Fiberglass Other
Liquid Level in tank X Normal Below Normal Above Normal
Access opening in tank One X Two Three None
Number of risers X One Two Three None
Condition of baffles and or sanitary tees:
Inlet baffle or "T" X Present and functional Not functional None present Not Visible
Outlet baffle or "T" X Present and functional Not functional None present Not Visible
Tank was pumped X Yes No (if no please explain below
Is system adequately sized for # of Bedrooms X Yes No # of Bedrooms:
Is system adequately sized for # of Bathrooms X Yes No # of Bathrooms:
System working Properly X Yes No (if no please explain below)

Additional Comments / Repairs needed:

Septic systems are subterranean, it is impossible to determine their overall condition. No prediction can be made as to when or if a system might fail.
This report comments on the workability of the system on the day of the inspection only, and is in no way intended to be a warranty.
Workability can be altered by factors such as excessive rainfall, heavy water usage, faulty plumbing, neglect or physical damage to the system. All tanks require pumping maintenance.

Inspected by: Robb Harter Date: 10-06-09



Robert Francois
504 East Butler
Manchester, Ia
52057

9-29-08