Book 2016 Page 1377
Document 2016 GWH-1377 Type 53 001 Pages 6
Date 5/31/2016 Time 10:15:03AM
Rec Amt $.00

Daneen Schindler, RECORDER/REGISTRAR
DELAWARE COUNTY IOWA

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

TRANSFEROR:

Name Thomas R. Glanz

Address 985 Arica Ave., Marion, Iowa 52302

Number and Street or RR | City, Town or P.O. | State | Zip

TRANSFEREE:

Name Nicholas M. Farrell

Address 33rd Ave, Shellsburg, Iowa 52332

Number and Street or RR | City, Town or P.O. | State | Zip

Address of Property Transferred:
26041 224th Ave, Delhi, Iowa 52223

Number and Street or RR | City, Town or P.O. | State | Zip

Legal Description of Property: (Attach if necessary) Mobile Home & enclosed porch on LL of Cooey; VIN#NEB1000W 30-88-4 Parcel # 220-30-01-002-09

1. **Wells (check one)**
   - ✓ There are no known wells situated on this property.
   - ___ There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.
2. **Solid Waste Disposal (check one)**
   - ✓ There is no known solid waste disposal site on this property.
   - ___ There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.
3. **Hazardous Wastes (check one)**
   - ✓ There is no known hazardous waste on this property.
   - ___ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.
4. **Underground Storage Tanks (check one)**
   - ✓ There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
   - ___ There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. **Private Burial Site (check one)**
   - ✓ There are no known private burial sites on this property.
   - ___ There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. **Private Sewage Disposal System (check one)**
   - ___ All buildings on this property are served by a public or semi-public sewage disposal system.
   - ___ This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
   - ✓ There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
   - ___ There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
   - ___ There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
   - ___ There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
   - ___ This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]: _____.
   - ___ The private sewage disposal system has been installed within the past two years pursuant to permit number _____.

Information required by statements checked above should be provided here or on separate sheets attached hereto:

_____

_____

_____

_____

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.

Signature: Thomas L. Klaus (Transferor or Agent) Telephone No.: (319) 551-4227

Time of Transfer Inspection Report

Property Information

Current Owner: Tom Glanz

Buyer: _____ Realtor: N/A

Mailing Address: 985 Arica Ave Marion, IA 52302

Site Address/County: 26041 224th Ave Delhi, IA

Legal Description N/A

No. of bedrooms: 1 Last occupied: Present Records available: No

Permit/ installation date: N/A Separation distances (ok/no?): Ok

Septic System Information

Septic tank(s): Size: 750gal Material: Cement Condition: Good

Tank pumped? x Y ☐ N Date: 7/1/2014 Licensed pumper: Triple J Services

Septic/Trash/Processing tank: Size: N/A Material: N/A Condition: N/A

Tank pumped? N/A Date: N/A Licensed pumper: N/A

Aerobic treatment unit (ATU) mfgr N/A Size N/A

Tank pumped? N/A Date: N/A Licensed pumper: N/A

Maintenance contract? N/A Expiration date: N/A Service provider: N/A

Condition: N/A

Pump tanks/vaults: Type: N/A Size: N/A Condition: N/A

Distribution system: Distribution box No Outlets used N/A Condition: N/A

Header pipe(s): N/A No. of lines: 1 Pressure dosed? N/A

Secondary Treatment:

Length of absorption fields: 18ft Determined by: Probing & Digging

Condition of fields: Good Determined by: Digging & No Ponding

Type of trench material: 1" Clean

Size of sand filter: N/A Determined by: N/A

Vent pipes above grade? N/A Discharge pipe located? N/A

Effluent sample taken N/A Results: N/A

Media Filters: Type: N/A

Maintenance contract? N/A Expiration date: N/A Service provider: N/A

Condition: N/A

NPDES General Permit No. 4: Required? N/A Permitted? N/A NOI provided: N/A

Time of Transfer Inspection Report

Other components:

Alarms: N/A Working: N/A Disinfection: N/A Working: N/A

Control Box: N/A Timers: N/A Inspection Ports: N/A

Other components: N/A

Overall condition of the private sewage disposal system:

Report system status: System working properly at time of inspection

Explain (attach additional pages as needed):

Comments:

Site status at conclusion of Time of Transfer inspection:

- Verify that controls are set on the appropriate mode.
- Power is on to all components.
- Revisit all components to verify lids are secure.
- Gather all tools for removal from the site.
- Verify that no sewage is on the ground surface.

Using this worksheet, write a narrative report of the inspection results and attach a site sketch.

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified Inspector: Jason Brimeyer Date: 7-17-14

Name (print): Jason Brimeyer Certificate #: 9446

Address: 23775 Pilot Grove Rd

Phone #: 563-590-2471

Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office and to:

Iowa DNR
Private Sewage Disposal Program

July 1 2014

Tom Glanz


26041 224th Ave

Delhi, IA 52223

Time of transfer septic system inspection for 26041 224th Ave Delhi, IA 52223.

A septic system inspection was conducted at 26041 224th Ave Delhi, IA on July 1, 2014. The system includes a 750 gallon concrete septic tank and 18 feet of seepage fields. All the fixtures in the home discharge to the septic tank. The Field was short but the system was functioning properly at time of inspection.

The tank was opened and pumped at the time of the inspection. The tank and baffles were in good condition. Water was run into the system to simulate a heavy use condition. There was no rise in the effluent level indicating the fields were accepting the water. The fields are rock and pipe and were dug and found to be clean and dry. This system was properly functioning the day of the inspection.


HOUSE
86041
8'
21'
8'
3' deep
TRENCH
750 GAL
18'