Book 2016 Page 1971
Document 2016 GWH-1971 Type 53 001 Pages 5
Date 8/01/2016 Time 10:27:52AM
Rec Amt $.00

Daneen Schindler, RECORDER/REGISTRAR
DELAWARE COUNTY IOWA

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

TRANSFEROR:

Name Mitch W. Tanner

Address 24622 189th Avenue, Manchester, Iowa 52057

Number and Street or RR | City, Town or P.O. | State | Zip

TRANSFEREE:

Name Luke W. Livingston

Address 720 E Howard Street, Manchester, Iowa 52057

Number and Street or RR | City, Town or P.O. | State | Zip

Address of Property Transferred:
24622 189th Avenue, Manchester, Iowa 52057

Number and Street or RR | City, Town or P.O. | State | Zip

Legal Description of Property: (Attach if necessary) Lot Ten (10) and the South One-half (S½) of Lot Nine (9) of Cozy Cove Subdivision A Subdivision of Lot One (1) through Lot Seven (7) of Willie's Second Subdivision, being part of the SE1/4 of the NE1/4 of Section 15, and part of the NE1/4 of the SE1/4 of Section 15, and part of the NW1/4 of the NW1/4 of Section 14, (T88N), (R5W) of the Fifth Principal Meridian, Delaware County, Iowa, according to plat recorded in Book 7 Plats, Page 156.

1. **Wells (check one)**
   - X There are no known wells situated on this property.
   - ___ There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.
2. **Solid Waste Disposal (check one)**
   - X There is no known solid waste disposal site on this property.
   - ___ There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.
3. **Hazardous Wastes (check one)**
   - X There is no known hazardous waste on this property.
   - ___ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.
4. **Underground Storage Tanks (check one)**
   - X There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
   - ___ There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. **Private Burial Site (check one)**
   - Y There are no known private burial sites on this property.
   - ___ There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.
6. **Private Sewage Disposal System (check one)**
   - ___ All buildings on this property are served by a public or semi-public sewage disposal system.
   - ___ This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
   - X There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
   - ___ There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
   - ___ There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
   - ___ There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
   - ___ This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]: _____.
   - ___ The private sewage disposal system has been installed within the past two years pursuant to permit number _____.

Information required by statements checked above should be provided here or on separate sheets attached hereto:

_____

_____

_____

_____

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.

Signature: _____ Telephone No.: (563) 920-8009
(Transferor or Agent)

Time of Transfer Inspection Report (DNR Form 542-0191)

Property information

Current owner Mitch Tanner
Buyer Jennifer & Luke Livingston Realtor Teresa Turnis
Mailing address 720 E. Howard St Manchester IA 52057

Site Address/County 24622 198th Ave Delaware Manchester IA
Legal Description Milo Township Sec. 15 T-88-N R E W

No. of bedrooms 3 (4) (5?) Last occupied? Current Records available NO

Permit/installation date 1996 Separation distances ok/ no? yes

Septic system information

Septic tank(s): size 1000 material Cement condition good
Tank pumped? yes date 6-27-16 licensed pumper ST 347
Septic/trash/processing tank: size NO material NO condition NO
Tank pumped? X date X licensed pumper X

Aerobic treatment unit (ATU) mfgr X size X
Tank pumped? X date X licensed pumper X
Maintenance contract? X expiration date X service provider X
Condition X

Pump tanks/vaults: type X size X condition X

Distribution system: distribution box yes outlets used 3 condition good
Header pipe(s) X # of lines X Pressure dosed? X

Secondary treatment:
length of absorption fields approx 3 lines 80 each determined by previous installation
condition of fields good determined by
type of trench material rock + pipe

Size of sand filter X determined by X
Vent pipes above grade? X discharge pipe located? X
Effluent sample taken? X Results X

Media filters: type X
Maintenance contract? X expiration date X service provider X
Condition X

NPDES General Permit No. 4: required? X permitted? X NOI provided X

Other components:

Alarms X Working? X disinfection X working? X

Control box X Timers X inspection ports X

Other components X

Overall condition of the private sewage disposal system

Report system status Read Map

Explain (attach additional pages as needed):

Comments:

Site status at conclusion of Time of Transfer inspection:

- Verify that controls are set on the appropriate mode.
- Power is on to all components.
- Revisit all components to verify lids are secure.
- Gather all tools for removal from the site.
- Verify that no sewage is on the ground surface.

Using this worksheet, write a narrative report of the inspection results and attach a site sketch.

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified inspector: Scott Harbach Date: 7-21-16


Name (print): Scott Harbach Certificate #: 8815

Address: 2443 210th Ave, Delhi, IA

Phone # 563-920-7622

Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent, the county sanitarian/environmental health office in the county the inspection was conducted and to;

Iowa DNR Onsite Wastewater Program
502 E. 9th St.
Des Moines, IA 50319



Tank and D-box was uncovered. Baffles in tank and D-box appears to be in good condition. Hydraulically tested by running water for 40 minutes. There was no rise in the effluent level. Indicating the fields were accepting the water. All Fixtures went to Septic. This system was properly functioning the day of the inspection