SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 2, Township 90 N, Range 4 W, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in _____ in County Recorder's Office.
(book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: Did not find 1/2" Rebar Monument Evidence for reestablishing corner was existing fence lines and Record Survey Book 5, Page 31, by Vorseth L.S. 5205. Set 6"x8"x24" Limestone painted blaze orange and 1/2" rebar w/cap

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)





I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: John R Crawford
Name typed or printed: John R. Crawford
Date: 12/12/90 Reg. No. 7474

SEAL

REGISTERED LAND SURVEYOR
JOHN R. CRAWFORD
7474
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
W1/4	2	90	4

FILE No. 63-1489
RECORDING FEE $ 5.00
TRANSFER FEE $ _____

FILED FOR RECORD THE 31 DAY OF December, 1990 AT 11:34 O'CLOCK A. M. BOOK 1 PAGE 29

STATE OF IOWA, DELAWARE COUNTY
Joan Sheppard, Recorder
Cor. Mon.