UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 9, Township 90, Range 6, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in Book _____, Page _____.


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: Survey of part of boundary of Backbone State Park N 1/4 Sec. 9-90-6 - Found 4" Steel Post Base, Set 2 ½" Pipe w/ State Marker #14

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects. relevant monuments and physical conditions that will enable recovery of the corner.)





N

N 1/4

PROF. ENGR. & LAND SURVEYOR
PAUL H. HELLAND
6505
IOWA

66-1585
DELAWARE COUNTY IOWA
FILED
'91 JAN 11 PM 1 58
BOOK 1 PAGE 33
RECORDER
$5.00

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Paul H. Helland 12/31/90

REGISTERED LAND SURVEYOR NO. 6505

SEAL

List Corners to be Indexed

Corners	Section	Twp	Range
N 1/4	9	90	6

FILE No. 66-1585
RECORDING FEE $ 5.00
TRANSFER FEE $ _____

FILED FOR RECORD THE 11 DAY OF January, 1991 AT 1:58 O'CLOCK P. M. BOOK 1 PAGE 33

STATE OF IOWA, DELAWARE COUNTY
Joan Sheppard, Recorder
Cor, Mon,