SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 29, Township 88N, Range Four (4) West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in --- in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: No certificate on record. Set in line with NE Corner Section 20 and SE Corner Section 29. SE Corner Section 29 located in fence line 20.23 chains (1335.2 ft) east of found stone at SW Corner SE 1/4 - SE 1/4 Section 29 per County Survey Record No. 2, page 172. NE Corner SE 1/4 - NE 1/4 Section 29 located 26.0 feet south of found old fence corner per Plat Book A, pages 108 -109. Set NE Corner Section proportionate distance North of NE Corner SE 1/4 - NE 1/4. East - West Corner position supported by road at E 1/4 Corner Section 20 and property line trench at NE Corner SE 1/4 - NE 1/4 Section 29.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



SECTION 29
T88N, R4W



DATE OF FIELD WORK: 5/02/91

TSE NO: 90-08

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: David Gibbs
Name typed or printed:

Date: 5/03/91 Reg. No. 8419

SEAL

REGISTERED LAND SURVEYOR
J. DAVID GIBBS
8419
IOWA

List Corners to be Indexed

Corners	Section	Twp.	Range
NE	29	88N	4W

FILE No. 93-2611
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 9 DAY OF May, 19 91 AT 9:42 O'CLOCK A M. BOOK 1 PAGE 61

STATE OF IOWA, DELAWARE COUNTY
Joan Sheppard, Recorder
Corner Monument