SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 11, Township 87 N, Range 5 W, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in _____ in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)
Monument Description and Remarks: NE Corner SE 1/4 - Set 1/2" Rebar 0.4' below road surface

NW Corner SE 1/4 - Set 1/2" Rebar 0.4' below road surface

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: Daniel T. Crawford
Name typed or printed: Daniel T. Crawford, R.L.S.
Date: May 21, 1991 Reg. No. 8812

SEAL

REGISTERED LAND SURVEYOR
DANIEL T. CRAWFORD
8812
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
NE Corner SE 1/4	11	87N	5W
NW Corner SE 1/4	11	87N	5W

FILE No. 115-362
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 6 DAY OF August, 1991 AT 10:08 O'CLOCK A. M. BOOK 1 PAGE 83

STATE OF IOWA, DELAWARE COUNTY
Jane A. LLoyd, Recorder
Cor. Mon.