SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 25, Township 88 North, Range 5 West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in no corner certificate on file in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: Found pointed limestone at an old rotted corner post stump.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: Roger R. Mohn
Name typed or printed: Roger R. Mohn
Date: August 5, 1991 Reg. No. 10165

SEAL

LAND SURVEYOR
REGISTERED
ROGER R.
MOHN
10165
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
SW Cor.	25	88N	5W

FILE No. 116-405
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 9 DAY OF August, 19 91 AT 10:17 O'CLOCK A. M. BOOK 1 PAGE 86

STATE OF IOWA, DELAWARE COUNTY
Jane A. Lloyd, Recorder
Cor. Mon.