SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 24, Township 88 North, Range Five (5) West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in --- in County Recorder's Office.
(book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: No certificate recorded in the Office of the Delaware County Recorder. Found 1/2" diameter iron rod with RLS Cap No. 5227 at S 1/4 Corner. Found 1" diameter pipe at SW Corner.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)







SECTION 24
T88N, R5W

N

DATE OF FIELD WORK: 7/11/91

TSE NO: 91-36

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: J. David Gibbs
Name typed or printed: J. David Gibbs
Date: 7/18/91 Reg. No. 8419

SEAL

REGISTERED LAND SURVEYOR
J. DAVID GIBBS
8419
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
S 1/4	24	88N	5W
SW	24	88N	5W

FILE No. 118-476
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 20 DAY OF August, 1991 AT 10:30 O'CLOCK A.M. BOOK 1 PAGE 87

STATE OF IOWA, DELAWARE COUNTY
Jane A. Lloyd, Recorder
Cor Mon