SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 19, Township 88 North, Range Five (5) West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in --- in County Recorder's Office.
(book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: Found nail in centerline of gravel road in-line with north-south fence. Set 1/2" diameter iron rod with RLS Cap No. 8419. Note: See survey recorded in Plat Book 6, Page 7.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)







DATE OF FIELD WORK: 8/27/91 TSE NO: 91-48

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: J. David Gibbs
Name typed or printed: J. David Gibbs
Date: 8/28/91 Reg. No. 8419

SEAL

REGISTERED LAND SURVEYOR J. DAVID GIBBS 8419 IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
SE of NW 1/4	19	88N	5W

FILE No. 121-601
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 5 DAY OF September, 19 91 AT 9:55 O'CLOCK A. M. BOOK 1 PAGE 90

STATE OF IOWA, DELAWARE COUNTY
Jane A. Lloyd, Recorder
COR. MON.