SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 36, Township 88 N, Range 5 W, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in _____ (book, page, document number, etc.) in County Recorder's Office.

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: No current references on file.

W 1/4 Corner - Found 1/2" Rebar 30" deep, set 1/2" rebar

NE Corner, NW-SW - Set 1/2" Rebar with Cap

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: John R Crawford
Name typed or printed: John R. Crawford, R.L.S.
Date: 8/27/91 Reg. No. 7474

SEAL

REGISTERED LAND SURVEYOR
JOHN R. CRAWFORD
7474
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
W 1/4 Corner	36	88	5
NE Corner NW-SW	36	88	5

FILE No. 125-782
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 24 DAY OF September, 19 91 AT 3:31 O'CLOCK P M. BOOK 1 PAGE 92

STATE OF IOWA, DELAWARE COUNTY
Jane A. Lloyd, Recorder
Cor. Mon.