SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 13, Township 88N, Range 6W, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in N/A in County Recorder's Office.
(book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks:

NW Cor. Sec. 13 – Fd. 5/8" Smooth bar Set #5 Epoxy Rebar
N. 1/4 Cor. Sec. 13 – Fd. mail from 1970 IDOT CORNER STONE SURVEY in E & N-S. and E-W. Road R.O.W. Set 1/2" Rebar
S. 1/4 Cor. Sec 13 – Fd 1" Pipe (bent) Set 1/2" Rebar

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: Daniel T. Crawford
Name typed or printed: Daniel T. Crawford, R.L.S.
Date: March 23, 1992 Reg. No. 8812

SEAL

REGISTERED LAND SURVEYOR
DANIEL T. CRAWFORD
8812
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
N.W. Corner	13	88N	6W
N. 1/4 Corner	13	88N	6W
S. 1/4 Corner	13	88N	6W

FILE No. 173-2684
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 24 DAY OF March 19 92 AT 4:22 O'CLOCK P. M. BOOK 1 PAGE 114

STATE OF IOWA, DELAWARE COUNTY
Jane A. Lloyd, Recorder
COR. MON.