SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 18, Township 89 N, Range 5 W, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in _____ (book, page, document number, etc.) in County Recorder's Office.

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: No current references on file.


N 1/4 Corner - Found 5/8" diameter iron Pipe.

NE Corner - Found Iron Pipe.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)





I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: John R Crawford
Name typed or printed: John R. Crawford, R.L.S.
Date: 4/10/92 Reg. No. 7474

SEAL

REGISTERED LAND SURVEYOR
JOHN R. CRAWFORD
7474
IOWA

Corners	List Corners to be Indexed Section	Twp	Range
N 1/4 Corner	18	89	5
NE Corner	18	89	5

FILE No. 188-3301
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 7 DAY OF May, 19 92 AT 11:17 O'CLOCK A. M. BOOK 1 PAGE 121

STATE OF IOWA, DELAWARE COUNTY
Jane A. Lloyd, Recorder
Cor. Mon.