SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 18, Township 89 N, Range 5 W, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in no current references on file in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: Corner lost in river channel. Evidence of fences extending north and south from river channel. Lost corner re-established by single proportionate measurement on the line between W 1/4 of Section 18 and W 1/4 Corner of Section 7. Set 5/8" epoxy coated rebar with survey cap.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: John R Crawford
Name typed or printed: John R. Crawford, R.L.S.
Date: 4/10/92 Reg. No. 7474

SEAL

REGISTERED LAND SURVEYOR
JOHN R. CRAWFORD
7474
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
NW Corner	18	89	5

FILE No. 188-3302
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 7 DAY OF May, 19 92 AT 11:18 O'CLOCK A. M. BOOK 1 PAGE 122

STATE OF IOWA, DELAWARE COUNTY
Jane A. Lloyd, Recorder
Cor. Mon.