SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 36, Township 90 North, Range 3 West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in no certificate on file in County Recorder's Office.
(book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: Found broken limestone at the corner.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)








I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: Roger R. Mohn
Name typed or printed: Roger R. Mohn
Date: January 16, 1992 Reg. No. 10165

SEAL



List Corners to be Indexed

Corners	Section	Twp	Range
Center	36	90N	3W

FILE No. 203-127
RECORDING FEE $ No Fee
TRANSFER FEE $

FILED FOR RECORD THE 29 DAY OF June 19 92 AT 10:23 O'CLOCK A. M. BOOK 1 PAGE 133

STATE OF IOWA, DELAWARE COUNTY
Jane A. Lloyd, Recorder
Cor. Mon.