SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 24, Township 87 N, Range 6 W, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in No current references on file in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks:

NE Corner - Found "X" cut in PCC Pavement - Cut "X" deep and retied.

E 1/4 Corner - No evidence of corner monument due to highway reconstruction. Re-established corner location from road plans and right-of-way acquisition plats and set 5/8" epoxy coated rebar with cap and referenced.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: John R Crawford

Name typed or printed: John R. Crawford, R.L.S.

Date: 8/14/92 Reg. No. 7474

SEAL

REGISTERED LAND SURVEYOR
JOHN R. CRAWFORD
7474
IOWA

Corners	List Corners to be Indexed Section	Twp	Range
NE Corner	24	87	6
E 1/4 Corner	24	87	6

FILE No. 220-845
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 4 DAY OF September, 19 92 AT 4:22 O'CLOCK P M. BOOK I PAGE 171

STATE OF IOWA, DELAWARE COUNTY
Jane A. Lloyd, Recorder
COR. MON.