SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE


OF


Land Survey Monuments situated in Section Ten (10), Township 88 North, Range Six (6) West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in ---- in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)
Monument Description and Remarks: No certificates recorded in the Office of the County Recorder. East Quarter (E 1/4) found 5/8 inch iron rod. NW Corner of NE 1/4 - NE 1/4 was found 1 inch iron pipe.


PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)





SECTION 10
T88N, R6W



E 1/4 COR.

NW COR. NE 1/4 NE 1/4

DATE OF FIELD WORK: 11/23/92

TSE NO: 92-77

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: J. David Gibbs
Name typed or printed: J. David Gibbs
Date: 12/10/92 Reg. No. 8419

SEAL

REGISTERED LAND SURVEYOR
J. DAVID GIBBS
8419
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
E¼	10	T88N	R6W
NW of NE¼ NE¼	10	T88N	R6W

FILE No. 245-1838
RECORDING FEE $ $5.00
TRANSFER FEE $

FILED FOR RECORD THE 15 DAY OF Dec, 1992 AT 3:18 O'CLOCK P. M. BOOK 1 PAGE 180

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
COR.MON.