SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 10, Township 88 North, Range 3 West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in no corner certificate on file in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: Found "x" cut in P.C.C. pavement at the West ¼ Cor. as per survey plat of record. Established location and cut "x" in P.C.C. pavement at the southwest corner of Section 10 using measurements to the W¼ corner and lines of occupation at the NW corner of the SW¼-SW¼ and at the southwest corner of said Section 10.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: Roger R. Mohn
Name typed or printed: Roger R. Mohn
Date: December 18, 1992 Reg. No. 10165

SEAL

LAND SURVEYOR
REGISTERED
ROGER R.
MOHN
10165
IOWA

Corners	List Corners to be Indexed Section	Twp	Range
W¼ Cor.	10	88N	3W
SW Cor.	10	88N	3W

FILE No. 247-1912
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 23 DAY OF Dec, 1992 AT 1:30 O'CLOCK P. M. BOOK 1 PAGE 189

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
COR.MON.