SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 23, Township 89N, Range 6W, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in N/A (book, page, document number, etc.) in County Recorder's Office.

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks:


W. 1/4 Corner Section 23 - Found 3/4" iron pipe

SW corner Section 23 - Found 1 1/2" iron pipe


PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)









I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: Daniel T. Crawford

Name typed or printed: Daniel T. Crawford, R.L.S.

Date: 12/15/92 Reg. No. 8812

SEAL

REGISTERED LAND SURVEYOR
DANIEL T. CRAWFORD
8812
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
W. 1/4 Cor	23	89N	6W
SW Cor	23	89N	6W

FILE No. 253-2141
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 14 DAY OF Jan, 1993 AT 2:28 O'CLOCK P. M. BOOK 1 PAGE 190

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
Cor. Mon.