SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section Five (5), Township 89 North, Range Three (3) West of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in ---- in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: No Certificate recorded in the Office of the County Recorder. Found PK nail in asphalt at E 1/4 Corner and Southeast Corner of said Section 5.

PLAN - VIEW


(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



SE CORNER



SECTION 5
T89N, R3W



E 1/4 CORNER

DATE OF FIELD WORK: 3/8/93 & 3/12/93

TSE NO: 93-17

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: J. David Gibbs
Name typed or printed: J. David Gibbs
Date: 3/18/93 Reg. No. 8419

SEAL

REGISTERED LAND SURVEYOR
J. DAVID GIBBS
8419
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
E 1/4	5	89N	3W
SE	5	89N	3W

FILE No. 269-2759
RECORDING FEE $ 5.00
TRANSFER FEE $

FILED FOR RECORD THE 18 DAY OF March, 1993 AT 3:16 O'CLOCK P. M. BOOK 1 PAGE 206

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
Cor. Mon.