SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section Twenty-eight (28), Township 89 North, Range Five (5) West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in ---- in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: No certificate recorded in the Office of the County Recorder. Found concrete nail in asphalt at Southeast Corner. NW Corner of SW 1/4 of SE 1/4, set half way between center and S 1/4 Corner.

PLAN - VIEW


(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



SECTION 28
T89N, R5W



SW CORNER



NW COR. SW 1/4, SE 1/4

DATE OF FIELD WORK: 5/26/93

TSE NO: 93-31

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: J. David Gibbs
Name typed or printed: J. David Gibbs
Date: 7/15/93 Reg. No. 8419

SEAL

REGISTERED LAND SURVEYOR
J. DAVID GIBBS
8419
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
SE	28	89N	R5W
NW of SW, SE	28	89N	R5W

Corrected Cor. Mon. 1
For Release, See Book ---
Page 335 2/2/96

FILE No. 301-238
RECORDING FEE $ 6.00
TRANSFER FEE $ ----

FILED FOR RECORD THE 15 DAY OF July, 1993 AT 2:35 O'CLOCK P. M. BOOK 1 PAGE 219

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
Cor. Mon.