SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 18, Township 87 North, Range Six (6) West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in ---- in County Recorder's Office.
(book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: No Certificates of record in the Office of the Delaware County Recorder. Found concrete nail at NE Corner. Set N 1/4 Corner at proportionate distance (using 1884 County Survey) between NE and NW Corners and midway between road fences.

PLAN - VIEW


(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)





SECTION 18
T87N, R6W

N



DATE OF FIELD WORK: 5/14 & 6/11/93

TSE NO: 93-32

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: David Gibbs
Name typed or printed: J. David Gibbs
Date: 8/13/93 Reg. No. 8419

SEAL

REGISTERED LAND SURVEYOR
J. DAVID GIBBS
8419
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
NE	18	87N	6W
N 1/4	18	87N	6W

FILE No. 309-552
RECORDING FEE $ -0-
TRANSFER FEE $

FILED FOR RECORD THE 17 DAY OF August, 19 93 AT 4:33 O'CLOCK P M. BOOK 1 PAGE 226

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
Cor. Mon.