SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section Nine (9), Township 87 North, Range Three (3) West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in _____ in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: No Certificate Recorded in the Office of the County Recorder's Office. Set NE Corner of SW 1/4, NW 1/4 at intersection of W 1/4 Corner of NW 1/4 & E 1/4 Corner of NW 1/4 with N 1/4 Corner of NW 1/4 & S 1/4 Corner of NW 1/4. Set NE Corner of SE 1/4, NW 1/4 on line & 1/2 way between center of Section & North 1/4 Corner all of Section 9, T 87N, R3W.


PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



SECTION 9
T87N, R3W







DATE OF FIELD WORK: 6/17/93 7/21/93 7/26/93 8/11/93

TSE NO: 93-36

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: William H. Burger
Name typed or printed: William H. Burger

Date: 8/19/93 Reg. No. 12642

SEAL



List Corners to be Indexed

Corners	Section	Twp	Range
NE of SW¼ NW¼	9	T87N	R3W
NE of SE¼ NW¼	9	T87N	R3W