SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 10, Township 87 NORTH, Range 3 WEST, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in None in County Recorder's Office.
(book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: E1/4 CORNER, SECTION 10-T87N-R3W: Set 1/2"ϕ Rebar with cap @ Intersection of County Road Centerlines -as per Road Records.


SE CORNER, SECTION 10-T87N-R3W: Set 1/2"ϕ Rebar with cap from record survey.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



E1/4 CORNER, SECTION 10-T87N-R3W



SE CORNER, SECTION 10-T87N-R3W

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: Gary L. Casady
Name typed or printed: Gary L. Casady
Date: 11-3-93 Reg. No. 12532
My Registration Expires December 31, 1994

SEAL

PROFESSIONAL LAND SURVEYOR
GARY L. CASADY
12532
IOWA

List Corners to be Indexed			
Corners	Section	Twp	Range
E1/4	10	87N	3W
SE	10	87N	3W

FILE No. 333-1471
RECORDING FEE $ 6.00
TRANSFER FEE $

FILED FOR RECORD THE 10 DAY OF Nov, 19 93 AT 2:34 O'CLOCK P. M. BOOK 1 PAGE 240

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
Cor. Mon.