SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE


OF

Land Survey Monuments situated in Section 11, Township 87 NORTH, Range 3 WEST, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in NONE in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)
Monument Description and Remarks: E1/4 CORNER, SECTION 11-T87N-R3W: Set ½"ϕ Rebar with cap @ Intersection of County Road Centerlines - as per Road Records.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



E1/4 CORNER, SECTION 11-T87N-R3W

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: Gary L. Casady
Name typed or printed: Gary L. Casady
Date: 11-3-93 Reg. No. 12532
My Registration Expires December 31, 1994

SEAL

PROFESSIONAL LAND SURVEYOR
GARY L. CASADY
12532
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
E1/4	11	87N	3W

FILE No. 333-1472
RECORDING FEE $ 6.00
TRANSFER FEE $

FILED FOR RECORD THE 10 DAY OF Nov, 1993 AT 2:35 O'CLOCK P. M. BOOK 1 PAGE 241

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
Cor. Mon.