SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section Nineteen (19), Township 89 North, Range Five (5) West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in ---- in County Recorder's Office.
(book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: No Certificate recorded in the Office of the County Recorder. Found 1" diameter iron rod at NE Corner of SE 1/4 of NE 1/4. Set 1/2" diameter iron rod with cap 12642 at E 1/4 Corner midway between SE Corner and NE Corner.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)







DATE OF FIELD WORK: 11/29/93, 12/1/93, 12/3/93, 12/6/93, 12/10/93, 12/16/93 TSE NO: 93-89

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: William H. Burger
Name typed or printed: William H. Burger
Date: 1/3/94 Reg. No. 12642

SEAL

REGISTERED LAND SURVEYOR
WILLIAM H. BURGER
12642
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
E 1/4	19	T89N	R5W
NE of SE¼ NE¼	19	T89N	R5W

FILE No. 2-2186
RECORDING FEE $ 6.00
TRANSFER FEE $

FILED FOR RECORD THE 13 DAY OF January, 19 94 AT 4:09 O'CLOCK P M. BOOK 1 PAGE 249

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
Cor. Mon.