SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 33, Township 89 North, Range 3 West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in no corner certificate on file in County Recorder's Office.
(book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: Found PK nail in A.C.C. pavement. PK nail is over iron pin that is under the pavement.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)





I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: Roger R. Mohn
Name typed or printed: Roger R. Mohn
Date: January 27, 1994 Reg. No. 10165

SEAL

LAND SURVEYOR REGISTERED ROGER R. MOHN 10165 IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
NW Cor.	33	89N	3W

FILE No. 8-2405
RECORDING FEE $
TRANSFER FEE $

FILED FOR RECORD THE 7 DAY OF February, 19 94 AT 3:24 O'CLOCK P M. BOOK 1 PAGE 250

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
Cor. Mon.