SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section Nineteen (19), Township 87 North, Range 3 West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in ---- in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: South 1/4 Corner - Set 1/2" dia. rod w/cap 12642 - Used 1972 IDOT ties to reset monument.


PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



SECTION 19
T87N, R3W






DATE OF FIELD WORK: 3/31/94, 4/19/94, 4/22/94

TSE NO: 94-22

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: William H. Burger
Name typed or printed: William H. Burger
Date: 4/26/94 Reg. No. 12642

SEAL



List Corners to be Indexed

Corners	Section	Twp	Range
S 1/4	19	87N	3W

FILE No. 33-3348
RECORDING FEE $ 6.00
TRANSFER FEE $

FILED FOR RECORD THE 4 DAY OF May, 1994 AT 3:31 O'CLOCK P. M. BOOK 1 PAGE 264

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
Cor. Mon.