SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 2, Township 89 North, Range 4 West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in No references on file. in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks:

South 1/4 Corner - Dug and found 1/2" x 18" bolt with hex. head - Set 1/2" rebar with cap.

North Corner - No evidence of monument - Set 1/2" rebar with cap.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: John R. Crawford
Name typed or printed: John R. Crawford, R.L.S.
Date: 4/18/94 Reg. No. 7474

SEAL

REGISTERED LAND SURVEYOR
JOHN R. CRAWFORD
7474
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
North Corner	2	89	4
South 1/4 Corner	2	89	4

FILE No. 33-3360
RECORDING FEE $ 6.00
TRANSFER FEE $

FILED FOR RECORD THE 5 DAY OF May, 1994 AT 2:55 O'CLOCK P. M. BOOK 1 PAGE 267

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
Cor. Mon.