SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 15, Township 89 North, Range 6 West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in No ties on record in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: NE Corner - Dug and found stone(9"x6"x16") referenced in County Surveyor's Record April 19 and 20, 1900, just beneath roadway surface. Four (4) small stones (3"-5") were found around stone. Lowered 2.0 feet and set 5/8" rebar.

N 1/4 Corner - Dug 4' wide x 5' deep x 10' long trench in roadway, no evidence of corner. Reset from County Surveyor's Record April, 1900 (2,641.10' to NE Corner).

NW Corner - Dug in roadway, no evidence of corner. County Surveyor's Record April, 1900, and Original Notes indicate corner is west of existing road. Set 1/2" rebar (2,641.20' to N 1/4 Corner).

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: John R Crawford
Name typed or printed: John R. Crawford, R.L.S.
Date: 4/15/94 Reg. No. 7474

SEAL

REGISTERED LAND SURVEYOR
JOHN R. CRAWFORD
7474
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
N 1/4 Corner	15	89	6
NE Corner	15	89	6
NW Corner	15	89	6

FILE No. 33-3362
RECORDING FEE $ 6.00
TRANSFER FEE $

FILED FOR RECORD THE 5 DAY OF May, 1994 AT 2:57 O'CLOCK P. M. BOOK 1 PAGE 269

STATE OF IOWA, DELAWARE COUNTY
Deborah L. Peyton, Recorder
Cor. Mon.