SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 5, Township 88 North, Range 5 West, of the Fifth Principal Meridian, Delaware County, Iowa.
Previously recorded in no current references on file in County Recorder's Office.
(book, page, document number, etc.)
(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)
Monument Description and Remarks:

N 1/4 Corner - No physical evidence of corner due to highway grading. Re-established from IDOT Survey traverse. Set P-K in ACC surface in left half of north east-bound lane.

Center 1/4 Corner - Found wood corner post at location noted in Delaware County Record Book A, Pages 66-67, Set 1/2" Rebar w/cap.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: John R. Crawford
Name typed or printed: John R. Crawford, R.L.S.
Date: 3/8/94 Reg. No. 7474

SEAL

REGISTERED LAND SURVEYOR ★ JOHN R. CRAWFORD 7474 ★ IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
N 1/4 Corner	5	88	5
Center 1/4 Corner	5	88	5

FILE No. 33-3363	FILED FOR RECORD THE 5 DAY OF May, 19 94 AT 2:58	STATE OF IOWA, DELAWARE COUNTY
RECORDING FEE $ 6.00	O'CLOCK P. M. BOOK 1 PAGE 270	Deborah L. Peyton, Recorder
TRANSFER FEE $		Cor. Mon.