RECORDER
SEP 16 AM 10 90
2
31
$6.00
255-906

John R. Crawford, R.L.S. Crawford Engineering & Surveying, Inc. 319/334-7077

SLSI 9-94

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 7, Township 88 N, Range 6 W, of the Fifth Principal Meridian, Delaware County County, Iowa.
Previously recorded in no current references on record in County Recorder's Office.
(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: NE Corner - No evidence of corner in PCC pavement. Reestablished point fron reference ties in county engineer's office. Drilled hole in pavement and set 1/2" rebar with cap. Point is 0.90' east of centerline saw joint.

E 1/4 Corner - No evidence of corner in PCC pavement. Reestablished point from fence lines, 1970 road plans and survey recorded in Book 2, Page 107. Drilled hole in pavement and set 1/2" rebar with cap. Point is on centerline of pavement.

W 1/4 Corner - Found 3/4" smooth iron bar 4" deep in gravel surface.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this land surveying document was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: John R Crawford

Name typed or printed: John R. Crawford, R.L.S.

Date: 9/11/96 Reg. No. 7474

My registration renewal date is December 31, 1997

SEAL

REGISTERED LAND SURVEYOR JOHN R. CRAWFORD 7474 IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
NE Corner	7	88	6
E 1/4 Corner	7	88	6
W 1/4 Corner	7	88	6

DATE 9-16-96 BOOK 2 PAGE 31