DELAWARE COUNTY IOWA
FILED
2003 JAN 25 AM 10:01
BOOK 3008 PAGE 2993
DEBORAH L. PEYTON
DELAWARE CO RECORDER
6.00

Prepared by: SCHNEIDER Land Surveying and Planning, Inc. P.O. Box 105 Peosta, Iowa 52068 563-556-9055

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 36, Township 88 North, Range 3 West of the Fifth Principal Meridian, Delaware County, Iowa.

Previously recorded BOOK 2, PAGE 154 (NE corner, SE1/4, NE1/4)
(BOOK, PAGE / INST. NO. / CABINET, SLIDE)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: A 1/2" REBAR WAS FOUND AT THE NE CORNER OF THE SE1/4 OF THE NE1/4 OF SECTION 36 AS ILLUSTRATED IN SECTION CORNER CERTIFICATE RECORDED IN BOOK 2, PAGE 154. THE CORNER WAS RETIED TO ILLUSTRATE MODIFICATIONS TO THE EXISTING TIES DUE TO A FENCE CHANGE.

A 1/2" REBAR WITH CAP #12642 WAS FOUND AT THE E1/4 CORNER OF SECTION 36. THE REBAR WAS TIED AND USED AS THE E1/4 CORNER.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)





I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

David P. Schneider P.L.S. #14417 Date: 1/20/2003
My license renewal date is December 31, 2003.

Pages or sheets covered by this seal: THIS SHEET ONLY

SCHNEIDER
Land Surveying & Planning, Inc.
P.O. Box 105 Peosta, Iowa 52068
Ph. #563-556-9055 Fax#563-556-9054

LICENSED LAND SURVEYOR
DAVID P. SCHNEIDER
#14417
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
NE CORNER SE1/4, NE1/4	36	88N	3W
E1/4	36	88N	3W

JOB NO. 505
BOOK 2003 PAGE 2993