DELAWARE COUNTY IOWA
FILED
2003 JN 25 AM 10: 58
BOOK 3 PAGE 3012
DEBORAH L. PEYTON
DELAWARE CO. RECORDER
6.00

JOHN R. CRAWFORD P.E. & L.S. Crawford Engineering & Surveying, Inc., Independence, Iowa 319/334-7077

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 3, Township 89 North, Range 6 West, of the Fifth Principal Meridian, Delaware County, Iowa.

Previously recorded in N/A in County Recorder's Office.

Monument Description and Remarks:

Reason for preparing certificate: Current certificate not on file.

Evidence and detailed procedure used to establish corner position: S 1/4 Corner - Recovered corner position from local evidence; SE Corner, W 1/2 SE 1/4 - Set corner at midpoint between S 1/4 and SE Corner; SE Corner - Recovered corner position from local evidence.


Monumentation found or placed: S 1/4 Corner; SE Corner W 1/2 SE 1/4; and SE Corner - Set 1/2" rebar with YPC


Extent of search for monument: N/A

PLAN-VIEW


(Show a minimum of three reference ties to durable physical objects, relevent monuments and physical conditions that will enable recovery of the corner).

S 1/4 Corner
Section 3-89-6
Set 1/2" Rebar






SE Corner, W 1/2 SE 1/4
Section 3-89-6
Set 1/2" Rebar



SE Corner
Section 3-89-6
Set 1/2" Rebar



I hereby certify that the survey work was completed and this land surveying document was prepared by me or under my direct personal supervision and that I ama duly licensed land surveyor under the laws of the State of Iowa.


Signature: John R Crawford

JOHN R. CRAWFORD P.E. & L.S.

Date: 6-19-03 Reg. No. 7474

My license renewal date is December 31, 2003

SEAL



List Corners to be Indexed

Corners	Section	Twp.	Range
S 1/4 Corner	3	89 N	6 W
SE Corner	3	89 N	6 W
SE Corner, W 1/2, SE 1/4	3	89 N	6 W

BOOK 2003 PAGE 3012