DELAWARE COUNTY IOWA
FILED
2003 OCT 14 AM 11:27
BOOK 2003 PAGE 4971
DEBORAH L. FRANK
DELAWARE COUNTY AUDITOR
Ca'll

TeKIPPE ENGINEERING, P.C., 128 South Vine Street, West Union, Iowa 52175 Phone (563) 422-5131

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 9, Township 90 North, Range 5 West of the Fifth Principal Meridian, Delaware County, Iowa.

Previously recorded in none in County Recorder's Office.
(book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: **NE Corner of NE 1/4 – NE 1/4**
Found 1/2" ø Rebar w/ Orange Plastic Cap 10165, from information on a survey and plat made by Roger Mohn, Recorded June 21, 1989, in Plat Book 6, Page 47

PLAN – VIEW

Project Number 03621.LS
FB. Honey Creek Twp. 1 PG.5

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)





NE Corner of the NE 1/4
Found 1/2" ø Rebar w/PLS 10165

LICENSED LAND SURVEYOR
PAUL R. HEROLD
15525
IOWA

I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

Paul R Herold 10-10-03
Paul R. Herold Date
License number 15525
My license renewal date is December 31, 2004.
Sheets covered by this seal: Individual

List Corners to be Indexed

Corners	Section	Twp.	Range
NE	9	90	5