DELAWARE COUNTY IOWA
FILED
2003 DE -2 AM 8:59
BOOK 3 PAGE 5575
DEBORAH L. TAYLOR
DELAWARE CO. AUDITOR
11.00

Part in Tray

TeKIPPE ENGINEERING, P.C., 128 South Vine Street, West Union, Iowa 52175 Phone (563) 422-5131

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 24, Township 90 North, Range 4 West of the Fifth Principal Meridian, DELAWARE County, Iowa.
Previously recorded in none in County Recorder's Office.
(book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: **SW Corner NW 1/4 – SE 1/4 Section 24 T90N R4W:** Set 1/2"ø rebar w/2"ø aluminum cap PLS 15525 equidistant and on line between the S 1/4 Corner and the Center of the Section.


NE Corner SE 1/4 – SE 1/4 Section 24 T90N R4W: Found 1/2" square twisted iron bar at the intersection of the centerlines of 280th Ave. and 137th St.

PLAN – VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



SW Corner NW 1/4 – SE 1/4 Section 24 T90N R4W
Set 1/2"ø rebar w/2"ø aluminum cap PLS 15525



NE Corner SE 1/4 – SE 1/4 Section 24 T90N R4W
Found 1/2" square twisted iron bar

LICENSED LAND SURVEYOR
PAUL R. HEROLD
15525
IOWA

I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

Paul R. Herold 11-24-03
Paul R. Herold Date
License number 15525
My license renewal date is December 31, 2004.
Sheets covered by this seal: Individual

List Corners to be Indexed

Corners	Section	Twp.	Range
SW–NW–SE	24	90N	4W
NE–SE–SE	24	90N	4W

X:\Section Corners\Sec. 24\24-90-4rt.dwg
Project Number 03642.LS
FB. Elk Twp. 1 PG. 1–5

BOOK 2003 PAGE 5575