DELAWARE COUNTY IOWA
FILED
2004 MR 30 PM 1:10
BOOK 2004 PAGE 1008
DEBORAH L PENTON
DELAWARE CO RECORDER
11.00

Prepared by: SCHNEIDER Land Surveying and Planning, Inc. P.O. Box 105 Peosta, Iowa 52068 563-556-9055

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 14, Township 89 North, Range 4 West of the Fifth Principal Meridian, Delaware County, Iowa.


Previously recorded (NONE OF RECORD).
(BOOK, PAGE / INST. NO. / CABINET, SLIDE)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: A NAIL WAS FOUND AT THE S1/4 CORNER OF SEC. 14, T89N, R4W. THE NAIL WAS TIED AND USED AS THE S1/4 CORNER. A MAG NAIL IN CHISELED 'X' IN PAVEMENT WAS FOUND AT THE E1/4 CORNER OF SEC. 14, T89N, R4W. THE MAG NAIL WAS TIED AND USED AS THE E1/4 CORNER.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

David P. Schneider P.L.S. #14417 Date: 3/16/2004
My license renewal date is December 31, 2005.

Pages or sheets covered by this seal: THIS SHEET ONLY

SCHNEIDER
Land Surveying & Planning, Inc.
P.O. Box 105 Peosta, Iowa 52068
Ph. #563-556-9055 Fax#563-556-9054

LICENSED LAND SURVEYOR
DAVID P. SCHNEIDER #14417
IOWA

List Corners to be Indexed

Corners	Section	Twp	Range
S1/4	14	89N	4W
E1/4	14	89N	4W

JOB NO. 641SCC
BOOK 2004 PAGE 1008