Book 2016 Page 3136
Document 2016 GWH-3136 Type 53 001 Pages 6
Date 11/10/2016 Time 8:37:33AM
Rec Amt $.00

Daneen Schindler, RECORDER/REGISTRAR
DELAWARE COUNTY IOWA

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

TRANSFEROR:

Name Kay Marie and Raymond A. Tauke

Address 2401 300th Avenue, Earlville, IA 52041

Number and Street or RR | City, Town or P.O. | State | Zip

TRANSFEREE:

Name Nathan M. and Jessica R. Goedken

Address 2676 220th Avenue, Delhi, IA 52223

Number and Street or RR | City, Town or P.O. | State | Zip

Address of Property Transferred:
2401 300th Avenue, Earlville, IA 52041

Number and Street or RR | City, Town or P.O. | State | Zip

Legal Description of Property: (Attach if necessary) Parcel 2016-74 in the Southeast Quarter of the Southeast Quater of Section 8, Township 88 North, Range 3 West of the 5th P.M., Delaware County, Iowa, AND Parcel 2016-75 in the North Half of the Northeast Quarter of Section 17, Township 88 North, Range 3 West of the 5th P.M., Delaware County, Iowa, according to plat recorded in Book 2016, Page 2967

1. **Wells (check one)**
   - ___ There are no known wells situated on this property.
   - _X_ There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.
2. **Solid Waste Disposal (check one)**
   - _X_ There is no known solid waste disposal site on this property.
   - ___ There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.
3. **Hazardous Wastes (check one)**
   - _X_ There is no known hazardous waste on this property.
   - ___ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.
4. **Underground Storage Tanks (check one)**
   - _X_ There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
   - ___ There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. **Private Burial Site (check one)**
   - X There are no known private burial sites on this property.
   - ___ There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. **Private Sewage Disposal System (check one)**
   - ___ All buildings on this property are served by a public or semi-public sewage disposal system.
   - ___ This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
   - X There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
   - ___ There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
   - ___ There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
   - ___ There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
   - ___ This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]: _____.
   - ___ The private sewage disposal system has been installed within the past two years pursuant to permit number _____.

Information required by statements checked above should be provided here or on separate sheets attached hereto:

Active well located approximately 120 feet south of house.

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.

Signature: Raymond A. Tauke (Transferor or Agent) Telephone No.: (563) 590-1748

FILE WITH RECORDER **DNR form 542-0960 (July 18, 2012)**

Time of Transfer Inspection Report (DNR Form 542-0191)

Property information

Current owner RAY TAUKE
Buyer _____ Realtor _____
Mailing address 2401 300 AVE EARLVILLE 52040

Site Address/County 2401 300th Ave Earlville, Ia 52041
Legal Description _____

No. of bedrooms 3 Last occupied? NOW Records available Yes

Permit/installation date 2008 Separation distances ok/ no? OK

Septic system information

Septic tank(s): size 1000 material CONCR condition OK
Tank pumped? Yes date 9-10-10 licensed pumper JS&
Septic/trash/processing tank: size 1000 material CONCR condition GOOD
Tank pumped? Yes date 9-10-10 licensed pumper JS&

Aerobic treatment unit (ATU) mfgr — size _____
Tank pumped? _____ date _____ licensed pumper _____
Maintenance contract? — expiration date _____ service provider _____
Condition _____

Pump tanks/vaults: type — size _____ condition _____

Distribution system: distribution box 4 outlets used 4 condition GOOD
Header pipe(s) — # of lines — Pressure dosed? NO

Secondary treatment:
length of absorption fields 4X75FT determined by PROB
condition of fields GOOD determined by PROB
type of trench material CHAMB

Size of sand filter — determined by _____
Vent pipes above grade? — discharge pipe located? _____
Effluent sample taken? — Results _____

Media filters: type —
Maintenance contract? _____ expiration date _____ service provider _____
Condition —

NPDES General Permit No. 4: required? _____ permitted? _____ NOI provided _____

Time of Transfer Inspection Worksheet

Other Components

Alarms _____ Working? _____ Disinfection _____ Working? _____

Control Box _____ Timers_____ Inspection Ports _____

Other Components _____

_____

Overall condition of the private sewage disposal system

Acceptable? X Unacceptable? _____

Explain (attach additional pages as needed): All in good working condition.

Comments: Keep Pump each 3-5 years.

Site status at conclusion of Time of Transfer inspection:

Verify that controls are set on the appropriate mode.
Power is on to all components.
Revisit all components to verify lids are secure.
Gather all tools for removal from the site.
Verify that no sewage is on the ground surface.

Using this worksheet, write a narrative report of the inspection results.

Submit a copy of this report, including your narrative, to the city/county environmental health office, the DNR and the county Recorder in the county where the inspection was conducted.

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified Inspector: _____ Date: 9-10-16

Name (print): Robb Harter Certficate #: 358

Address: 3031 160th Street Dyersville, Iowa 52040

Phone # 563-542-1010

Homeowners: Ray & Kay Tanke
2401 300th Ave
Earlville, Iowa 52041

Age of Property 1900
Occupied
(Yes) or No

Inspection Co: Harter Custom Pumping
3031 160th St. Dyersville Ia 52040
Date of Inspection: 11-10-16

Does this evaluation/inspection meet the requirements of state and local agencies? Yes ✓ No ___ N/A ___

Section 1:

Location of the system: East West (North) South
Was Water run into the system for 30 minutes? (Yes) No
Does the septic tank have a visible riser? Yes (No)
Estimated size of tank 1000 Gallons *Basis for estimate*
What is the separation between well and septic? 160
Does the separation of the well and septic meet local requirements? (Yes) No N/A

Section2: Disposal Field

Any evidence of malfunction (No) Yes (Please check all applicable observed conditions)
___ Wet Areas ___ Unusual green/lush vegetation
___ Liquid Discharges to surface ___ Discharge pipe of unknown origin
___ Localized surface settling ___ Other (Describe below)

Septic Tank:

Septic tank material X Concrete Fiberglass Other
Liquid Level in tank X Normal Below Normal Above Normal
Access opening in tank X One Two Three None
Number of risers X One Two Three None
Condition of baffles and or sanitary tees:
Inlet baffle or "T" X Present and functional Not functional None present Not Visible
Outlet baffle or "T" X Present and functional Not functional None present Not Visible
Tank was pumped X Yes No (if no please explain below
Is system adequately sized for # of Bedrooms X Yes No # of Bedrooms:
Is system adequately sized for # of Bathrooms X Yes No # of Bathrooms:
System working Properly (Yes) No (if no please explain below)


Additional Comments / Repairs needed:

Kept TANK Pump Over 3-5-Years


Septic systems are subterranean, it is impossible to determine their overall condition. No prediction can be made as to when or if a system might fail.
This report comments on the workability of the system on the day of the inspection only, and is in no way intended to be a warranty.
Workability can be altered by factors such as excessive rainfall, heavy water usage, faulty plumbing, neglect or physical damage to the system. All tanks require pumping maintenance.

Inspected by: [signature] Date: 8-10-16

Beacon™ Delaware County, IA



Overview



Legend

- Corporate Limits
- Political Township

Parcels

- <all other values>
- Yes

Roads

Parcel ID	200080001100	**Alternate ID**	n/a	**Owner Address**	Tauke, Kay Marie
Sec/Twp/Rng	8-88-3	**Class**	A		2401 300th Ave
Property Address	2401 300TH AVE EARLVILLE	**Acreage**	1.99		Earlville, IA 52041
District	NORTH FORK				
Brief Tax Description	PARCEL 2016-74 PT SE SE (Note: Not to be used on legal documents)				

TAOK to D Box 80Ft

2015 Orthophotography Disclaimer: The information in this web site represents current data from a working file which is updated continuously. Information is believed reliable, but its accuracy cannot be guaranteed. No warranty, express or implied, is provided for the data herin, or its use. Special assessments not shown.

Date created: 11/8/2016
Last Data Uploaded: 11/8/2016 1:18:45 AM

Developed by
The Schneider Corporation