

Book 2020 Page 2199 Type 43 001 Pages 8 Date 6/23/2020 Time 12:15:24PM Rec Amt \$.00

INDX ANNO **SCAN** 

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

### **REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT**

TO BE COMPLETED BY TRANSFEROR

<b>TRANSF</b>	EROR:						
Name	Twyla J. Jackson						
Address 322 S. 10th Avenue, Winterset, IA 50273							
	Number and Street or RR	City, Town or P.O.	State	Zip			
TRANSF	EREE:						
Name	John T. Nicoletto						
Address 4330 Franklin Avenue, Des Moines, IA 50310							
	Number and Street or RR	City, Town or P.O.	State	Zip			
	of Property Transferred: k Tower Road, Winterset, IA 5	50273					
Nur	mber and Street or RR	City, Town or P.O.	State	Zip			
1. Wells	(check one)						
<u>X</u> T/ T/ st	here are no known wells situ here is a well or wells situate ated below or set forth on ar	ed on this property. The type(s), len attached separate sheet, as nec		tus are			
<u>X</u> T		e disposal site on this property. al site on this property and informa	ation related thereto is p	orovided			
	dous Wastes (check one)		•				
TI	here is no known hazardous here is hazardous waste on ttachment #1, attached to th	this property and information rela-	ted thereto is provided i	in			
4. Under	rground Storage Tanks (c <mark>l</mark>	neck one)					
sr		ound storage tanks on this propert tor fuel tanks, most heating oil tan					
		age tank on this property. The typested below or on an attached sepa					

Telephone No.: (515) 462-3424

#### **EXHIBIT "A"**

Lot One (1) of Jackson Subdivision, located in the Southeast Quarter (1/4) of the Southwest Quarter (1/4) and in the Southwest Quarter (1/4) of the Southeast Quarter (1/4) of Section Seven (7), Township Seventy-five (75) North, Range Twenty-seven (27) West of the 5<sup>th</sup> P.M., Madison County, Iowa, and in Lot Eight (8) of the Northeast Quarter (1/4) of the Northwest Quarter (1/4) of Section Eighteen (18), Township Seventy-five (75) North, Range Twenty-seven (27) West of the 5th P.M., Madison County, Iowa.



**Property Information** 

Current Owner: Twyla Jackson				
Buyer: John Nicoletto Realtor: Toni Tindell				
Mailing Address: 322 South 10 <sup>th</sup> Ave. Winterset, IA 50273				
Site Address/County: 2408 Clark Tower Rd Winterset, IA 50273 Madison County				
Legal Description SE SW EX .36A RD & EX 3A NE COR & EX PARCEL C WEST OF HWY				
No. of bedrooms: 3 Last occupied: December 2019 Records available: Yes				
Permit/ installation date: 1943 10-23-2012 Separation distances (ok/no?): Good at this time				
Septic System Information				
Septic tank(s): Size: 1500 gallon Material: Plastic Condition: Good at this time				
Tank pumped? X Y N Date: 4/16/2020 Licensed pumper: River to River				
Septic/Trash/Processing tank: Size: Material: Condition:				
Tank pumped?				
Aerobic treatment unit (ATU) mfgr Size				
Tank pumped?				
Maintenance contract?				
Condition:				
Pump tanks/vaults: Type: Size: Condition:				
Distribution system: Distribution box Outlets used Condition:				
Header pipe(s): No. of lines: Pressure dosed?				
Secondary Treatment: EcoFlo Peat Filter				
Length of absorption fields: Determined by:				
Condition of fields: Determined by:				
Type of trench material:				
Size of sand filter: Determined by:				
Vent pipes above grade?				
Effluent sample taken System does not discharge Results:				
Media Filters: Type: Peat Filter				
Maintenance contract?				
Condition: Good at this time				
NPDES General Permit No. 4: Required?				
4/2010 cmz/dag				



Other components:							
Alarms: YN Working: YN Disinfection:	]Y⊠N '	Working: YNN					
Control Box: Timers: Inspection	Ports:	and the second s					
Other components:							
Overall condition of the private sewage disposal system: working as inten-	nded at this tir	ne					
Report system status: Working as intended at this time							
Explain (attach additional pages as needed): See attached							
Comments:							
	<del></del>						
Site status at conclusion of Time of Transfer inspection:							
<ul> <li>Verify that controls are set on the appropriate mode.</li> <li>Power is on to all components.</li> <li>Revisit all components to verify lids are secure.</li> <li>Gather all tools for removal from the site.</li> <li>Verify that no sewage is on the ground surface.</li> </ul>							
Using this worksheet, write a narrative report of the inspection results and	d attach a site	sketch.					
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.							
Signature of Certified Inspector:	Date:	4/24/2020					
Name (print): Dustin Tromblay	Certificate #	: 12293					
Address: River to River, PO Box 460 Waukee, IA 50263							
Phone #: 515-987-3913							
Provide a copy of this report, the narrative report and sketch to the seller/a ordering the inspection, the county sanitarian/environmental health office	~ .	gent or the person					

Iowa DNR
Private Sewage Disposal Program
502 E 9<sup>th</sup> St
Des Moines IA 50319
4/2010 cmz/dao



#### **Property Information**

Current Owner: I wyla Jackson						
Buyer: John Nicoletto	Realtor: Toni Tindell					
Mailing Address: 322 South 10 <sup>th</sup> Ave. Winterset, IA 50273						
Site Address/County: 2408 Clark Tower Rd Winterset,	IA 50273 Madison County					
Legal Description SE SW EX .36A RD & EX 3A NE COR & EX PARCEL C WEST OF HWY						
No. of bedrooms: 3 Last occupied:	December 2019 Records available: Yes					
Permit/ installation date: 1943 10-23-2012 Separation distances (ok/no?): Good at this time						
Septic System Information						
Septic tank(s): Size: 1500 gallon Material:	Plastic Condition: Good at this time					
Tank pumped? X Y N Date: 4/16/2020	Licensed pumper: River to River					
Septic/Trash/Processing tank: Size: Material: Condition:						
Tank pumped?	Licensed pumper:					
Aerobic treatment unit (ATU) mfgr	Size					
Tank pumped?	Licensed pumper:					
Maintenance contract?						
Condition:						
Pump tanks/vaults: Type: Size:	Condition:					
Distribution system: Distribution box	Outlets used Condition:					
Header pipe(s): No. of	lines: Pressure dosed?					
Secondary Treatment: EcoFlo Peat Filter						
Length of absorption fields:	Determined by:					
Condition of fields:	Determined by:					
Type of trench material:						
Size of sand filter:	Determined by:					
Vent pipes above grade?	Discharge pipe located?					
Effluent sample taken System does not discharge	Results:					
Media Filters: Type: Peat Filter						
Maintenance contract?						
Condition: Good at this time						
NPDES General Permit No. 4: Required?  YN N	Permitted?  \[ Y \Bigsim N \ NOI provided: \[ NA \]					
4/2010 cmz/dao	DNR Form 542-0191					



Other components:							
Alarms: YN Working: YN Disinfection: YN Working: YN N							
Control Box: Timers: Inspection Ports:							
Other components:							
Overall condition of the private sewage disposal system: working as intended at this time							
Report system status: _Working as intended at this time							
Explain (attach additional pages as needed): See attached							
Comments:							
Site status at conclusion of Time of Transfer inspection:							
Verify that controls are set on the appropriate mode.							
<ul> <li>Power is on to all components.</li> <li>Revisit all components to verify lids are secure.</li> </ul>							
Gather all tools for removal from the site.							
Verify that no sewage is on the ground surface.							
Using this worksheet, write a narrative report of the inspection results and attach a site sketch.							
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.							
97 6 1							
Signature of Certified Inspector:  Date: 4/24/2020							
Signature of Certified Inspector:    Complete   Certified Inspector   Date: 4/24/2020   Date: 4/24/202							
Name (print): Dustin Tromblay Certificate #: 12293							
Address: River to River, PO Box 460 Waukee, IA 50263							
Phone #:515-987-3913							
Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office and to:							

Iowa DNR
Private Sewage Disposal Program
502 E 9<sup>th</sup> St
Des Moines IA 50319



#### **ONSITE SEPTIC SOLUTIONS**

Maintenance, Repair, Design & Problem Solving

4/24/2020

RE: Time of Transfer

Address: 2408 Clark Tower Rd, Winterset, IA

Seller: Twyla Jackson

To whom it may concern,

On April 16, 2020, River to River pumped and inspected the onsite wastewater treatment system (OWTS) at the above location. The dwelling is assessed as a 3-bedroom, single-family home. All plumbing goes to the OWTS at this time.

The septic tank is in good condition and is working properly at this time. The peat filter is in good condition at this time as well. The peat inside looks about 30% degraded. A sample was not collected at this time, discharge looked completely dry even after a hydraulic load test. All points of the septic system were load tested and all passed. System is in good condition and is working properly at this time.

This report is an assessment of the current functioning of the OWTS, not a guarantee of its future performance. If you have any questions, please call.

Sincerely,

**Dustin Tromblay** 

Certified Inspector #12293

River to River Onsite Septic Solutions

515-987-3913