

Document 2020 GW2337

Book 2020 Page 2337 Type 43 001 Pages 5 Date 7/01/2020 Time 12:33:24PM

Rec Amt \$.00

I NDX ANNO SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

TRANSF				
Name	Chadwick D. Ecklor			
Address	2994 Putter Rd., Cabool, N	1O 65689		
	Number and Street or RR	City, Town or P.O.	State	Zip
TRANSF	EREE:			
Name	Kyle Van Zee			
Address	1239 Cottonwood Ave., Dexter, IA 50072			
	Number and Street or RR	City, Town or P.O.	State	Zip
	of Property Transferred: ttonwood Ave., Dexter, IA 5	50072		
Nur	mber and Street or RR	City, Town or P.O.	State	Zip
	<u> </u>			_

Legal Description of Property: (Attach if necessary)

Parcel "A", located in the Southeast Quarter (1/4) of the
Northeast Quarter (1/4) of Section Seventeen (17), Township Seventy-seven (77) North, Range Twenty-nine (29) West of the
5th P.M., Madison County, Iowa, containing 3.000 acres, as shown in Plat of Survey filed in Book 3, Page 557 on April 5, 2000 in the Office of the Recorder of Madison County, Iowa.

1. Wells (check one)

__ There are no known wells situated on this property.

★ There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Şolid Waste Disposal (check one)

X There is no known solid waste disposal site on this property.

There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

There is no known hazardous waste on this property.

___ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)

There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5.	Private Burial Site (check one)
	✓ There are no known private burial sites on this property.
	There is a private burial site on this property. The location(s) of the site(s) and known
	identifying information of the decedent(s) is stated below or on an attached separate sheet, as
	necessary.
6	Private Sewage Disposal System (check one)
٠.	All buildings on this property are served by a public or semi-public sewage disposal system.
	This transaction does not involve the transfer of any building which has or is required by law to
	have a sewage disposal system.
	There is a building served by private sewage disposal system on this property or a building
	without any lawful sewage disposal system. A certified inspector's report is attached which
	documents the condition of the private sewage disposal system and whether any modifications
	are required to conform to standards adopted by the Department of Natural Resources. A
	certified inspection report must be accompanied by this form when recording.
	There is a building served by private sewage disposal system on this property. Weather or
	other temporary physical conditions prevent the certified inspection of the private sewage
	disposal system from being conducted. The buyer has executed a binding acknowledgment
	with the county board of health to conduct a certified inspection of the private sewage disposal
	system at the earliest practicable time and to be responsible for any required modifications to
	the private sewage disposal system as identified by the certified inspection. A copy of the
	binding acknowledgment is attached to this form.
	There is a building served by private sewage disposal system on this property. The buyer has
	executed a binding acknowledgment with the county board of health to install a new private
	sewage disposal system on this property within an agreed upon time period. A copy of the
	binding acknowledgment is provided with this form.
	There is a building served by private sewage disposal system on this property. The building to
	which the sewage disposal system is connected will be demolished without being occupied. The
	buyer has executed a binding acknowledgment with the county board of health to demolish the
	building within an agreed upon time period. A copy of the binding acknowledgment is provided
	with this form. [Exemption #9]
	This property is exempt from the private sewage disposal inspection requirements pursuant to
	the following exemption [Note: for exemption #9 use prior check box]:
	The private sewage disposal system has been installed within the past two years pursuant to
	permit number
Inf	formation required by statements checked above should be provided here or on separate
eh	eets attached hereto:
J.,	eets attached hereto: 1 Pumpa SW Cor. of House
	a with the second
4	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
'n	20/ South of Barn
_	
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM
	AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
	4
Sid	gnature:
`	(Transferor of Agent)



Time of Transfer Inspection Report (DNR Form 542-0191)

rioparty miormation
Current owner Sheri Ecklor
Buyer Realtor
Mailing address
Site Address/County 1239 Cottonwood Ave Winterset TA Madison
Legal Description Some as address
No. of bedrooms 4 Last occupied? Still there Records available 405
Permit/installation date 6-9-03 Separation distances of no?
Septic system information
Septic tank(s): size 1500 gal material Condition Looks of Attles Tank pumped? Look date 4-16-2020 licensed pumper 1445 57455 Time Septic/trash/processing tank: size material condition Tank pumped? date kicensed pumper
Aerobic treatment unit (ATU) mfgr size Tank pumped? date licensed pumper Maintenance contract? expiration date service provider Condition
Pump tanks/vaults: type size condition Distribution system: distribution box plantic outlets used condition looks at at the
Header pipe(s) # of lines # Pressure dosed? 20 time
Secondary treatment: length of absorption fields 100ft x 4 determined by probe + Majo condition of fields 100K ok of this Time determined by probe 4 look afgrade type of trench material Chamber
Size of sand filter determined by Vent pipes above grade? discharge pipe located?
Effluent sample taken? Results
Media filters: type Maintenance contract? expiration date service provider Condition
NPDES General Permit No. 4: required? NOI provided



Time of Transfer Inspection Report

Other components:
Alarms Working? disinfection working?
Control box 10 Timers 100 inspection ports Rigges + Channel
Other components Kizem to top of ground on tank
Overall condition of the private sewage disposal system
Report system status Clear out next to house
Explain (attach additional pages as needed): has 2 Compartment lement tout
Comments: has fifter on out let Side
Verify that controls are set on the appropriate mode. Power is on to all components. Revisit all components to verify lids are secure. Gather all tools for removal from the site. Verify that no sewage is on the ground surface. Using this worksheet, write a narrative report of the inspection results and attach a site sketch. This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.
Signature of Certified inspector: <u>Ullen akes</u> Date: <u>4-17-2020</u> Name (print): <u>Allen Akers</u> Certificate #: <u>1023</u> Address: <u>220+ 175es at Winterset JA 50213</u> Phone # <u>515-462-1015</u>
Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent, the county sanitarian/environmental health office, county Recorder in the county the inspection was conducted and to;
Iowa DNR Onsite Wastewater Program 502 E. 9 th St. Des Moines, IA 50319

542-0191

1939 Cotton cod the