BK: 2020 PG: 3802

Recorded: 10/6/2020 at 9:27:36.0 AM

Pages 8

County Recording Fee: \$0.00 lowa E-Filing Fee: \$0.00 Combined Fee: \$0.00

Revenue Tax:

LISA SMITH RECORDER Madison County, Iowa

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

TRANSF				
Name Address	Madison County Auction 1204 W. Summit, Winters		 -	
/ ladicss	Number and Street or RR	City, Town or P.O.	State	Zip
TRANSF	FRFF.			
Name	Madison County Auction	Company, L.L.C.		
	1775 313th Street, Lorimo			
	Number and Street or RR	City, Town or P.O.	State	Zip
	of Property Transferred: Summit, Winterset, IA 502	73		
Nui	mber and Street or RR	City, Town or P.O.	State	Zip
T st 2. Solid T in	ated below or set forth on a Waste Disposal (check or here is no known solid wast here is a solid waste dispos Attachment #1, attached to	ted on this property. The type(s), lot in attached separate sheet, as nece ne) te disposal site on this property. teal site on this property and informato to this document.	essary.	
X TI At 4. Under X TI sr	ttachment #1, attached to th r ground Storage Tanks (c here are no known undergro	s waste on this property. this property and information relathis dis document.	/. (Note exclusions su	ıch as
TI	nere is an underground stor	age tank on this property. The typ sted below or on an attached separ	e(s), size(s) and any k rate sheet, as necessa	nown ary.

5.	Private Burial Site (check one)
	X There are no known private burial sites on this property.
	There is a private burial site on this property. The location(s) of the site(s) and known
	identifying information of the decedent(s) is stated below or on an attached separate sheet, as
	necessary.
6.	Private Sewage Disposal System (check one)
	All buildings on this property are served by a public or semi-public sewage disposal system.
	This transaction does not involve the transfer of any building which has or is required by law to
	have a sewage disposal system.
	X There is a building served by private sewage disposal system on this property or a building
	without any lawful sewage disposal system. A certified inspector's report is attached which
	documents the condition of the private sewage disposal system and whether any modifications
	are required to conform to standards adopted by the Department of Natural Resources. A
	certified inspection report must be accompanied by this form when recording.
	There is a building served by private sewage disposal system on this property. Weather or
	other temporary physical conditions prevent the certified inspection of the private sewage
	disposal system from being conducted. The buyer has executed a binding acknowledgment
	with the county board of health to conduct a certified inspection of the private sewage disposal
	system at the earliest practicable time and to be responsible for any required modifications to
	the private sewage disposal system as identified by the certified inspection. A copy of the
	binding acknowledgment is attached to this form.
	There is a building served by private sewage disposal system on this property. The buyer has
	executed a binding acknowledgment with the county board of health to install a new private
	sewage disposal system on this property within an agreed upon time period. A copy of the
	binding acknowledgment is provided with this form.
	There is a building served by private sewage disposal system on this property. The building to
	which the sewage disposal system is connected will be demolished without being occupied. The
	buyer has executed a binding acknowledgment with the county board of health to demolish the
	building within an agreed upon time period. A copy of the binding acknowledgment is provided
	with this form. [Exemption #9]
	This property is exempt from the private sewage disposal inspection requirements pursuant to
	the following exemption [Note: for exemption #9 use prior check box]:
	The private sewage disposal system has been installed within the past two years pursuant to
	permit number·
	and the second s
In	formation required by statements checked above should be provided here or on separate
S	heets attached hereto:
$\underline{\mathbf{T}}$	he well is located just East of the Northeast corner of the sale barn. Sellers make no representations or
W	arranties as to the quality, quantity or potability of the well water. The property is also served by rural
<u>w</u>	rater.
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM
	AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
	11 G 80 TOU KIG 790 9711
S	ignature: Thomas & Christian Telephone No.: 515-729-2711
٠	(Transferor or Agent)

5.

6.

GROUNDWATER HAZARD STATEMENT

ATTACHMENT #1

NOTICE OF WASTE DISPOSAL SITE

b.	Solid Waste Disposal (check one) There is a solid waste disposal site on this property, but no notice has been received from the Department of Natural Resources that the site is deemed to be potentially hazardous. There is a solid waste disposal site on this property which has been deemed to be potentially hazardous by the Department of Natural Resources. The location(s) of the site(s) is stated below or on an attached separate sheet, as necessary. Hazardous Wastes (check one) There is hazardous waste on this property and it is being managed in accordance with Department of Natural Resources rules. There is hazardous waste on this property and the appropriate response or remediation actions, or the need therefore, have not yet been determined.
<u>N/</u>	A
_	
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
S	ignature: Thona & Chutleur Telephone No.: 515729,2711

Addendum

1. Parcel "S" located in the West Half (1/2) of the Northwest Quarter (1/4) of the Northwest Quarter (1/4) of Section One (1), Township Seventy-Five (75) North, Range Twenty-eight (28) West of the 5th P.M., Madison County, Iowa, containing 17.03 acres, more or less, as shown in Plat of Survey filed in Book 2020, Page 3392 on September 9, 2020 in the Office of the Recorder of Madison County, Iowa.



Time of Transfer Impaction Report (DNR Form 542-0191)

Property information	n tan Orotals
Current comes MADISON CO Buyer DUN KNOW Marling madress 1204 W	Muction Rentals Summit Winter Jet Ja
Son Address Commo Same	and the state of t
N a bedrooms ○ Last occupied?	Still Records available NO
Permufustallation date Sep	varation distances ok/no?
Source system information	
Servic tank(s): size Uprox 1250 mail Tank pumped? Ues date 8-25 Septic/trash/processing tank: size Tank pumped? date	erial Concrete condition Fair -20 licensed pumper Wecgert # 2 material condition licensed pumper
Tank pumped? date Claimanance contract? expiration of	licensed pumper late service provider
Scorlifon The Ks/vaults: LVDC	size condition
	(A) condition
Header pipe(s)	= # of lines / Pressure dosed? ///
of fields Quarel absorption fields Quarel	determined by probetily
A material QOC	
and filter	determined by
above grade?	determined by discharge pipe located?
immple taken?	Results
type ce contract? expiration	date service provider
	many to the second of the seco
It No. 4: required?	permitted? NOI provided
	Page 1 of 2



Time of Transfer Inspection Report

Other components:	Water Condition	working?	
Alarms Working?			1 A
Control box Timer	inspection	ports	
Other components			
Overall condition of the private sewage d	lisposal system	Sace	o 4
Report system status See a	ida itional	3000	- • -
Explain (attach additional pages as neede	1 /		
Comments:			· · · · · · · · · · · · · · · · · · ·
_enmens.			
the status at conclusion of Time of Tran	sfer inspection:		
Verify that controls are se	et on the appropriate mode.		
Power is on to all compor Revisit all components to	nents. verify lids are secure.		•
(A)	val from the site. on the ground surface.	one	
wertsheet, write a narrative re			ketch.
tudestes the condition of the for at does not guarantee that	e private sewage disposal systems to function s	am at the time of satisfactorily.	
$\mathcal{O}_{\mathcal{O}_{\bullet}}$			121/20
A Condition inspector:	ike Harben	Date: Certificate #	945
	th St Cun	aming	
15 360-0	399	J	
this report, the parrativ	ve report and sketch to the se	ller/agent, buyer/a	gent or
the inspection, the co	ounty sanitarian/environment	ial health office, a	nd to:
	22.		
		25 - 15 - 15 - 15 - 15 - 15 - 15 - 15 -	

bath rooms
56 Co Co Septic TANK rosek & pipe 70an a coal

This is an older Septu System with conoredo I MNI tank was holding water! pumped out, it had very 1, H Sludge in the bottom of the TANK, of was working proper - + Ank Looks Good There was one hathered, D.c.c. et pipe, il was very alean with no siludge build up, Latteral was drydin very Good Condition