



Document 2021 GW3101

Book 2021 Page 3101 Type 43 001 Pages 7

Date 7/26/2021 Time 11:53:58AM

Rec Amt \$.00

INDX
ANNO
SCAN

LISA SMITH, COUNTY RECORDER
MADISON COUNTY IOWA

CHEK

**REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT
TO BE COMPLETED BY TRANSFEROR**

TRANSFEROR:

Name Perry D. Borntreger and Sarah O. Borntreger

Address 2909 Homestead Avenue, Lorimor, IA 50149

Number and Street or RR

City, Town or P.O.

State

Zip

TRANSFeree:

Name Andrew Herschberger

Address 3025 110th Street, Lorimor, IA 50149

Number and Street or RR

City, Town or P.O.

State

Zip

Address of Property Transferred:

1934 330th Street, Lorimor, IA 50149

Number and Street or RR

City, Town or P.O.

State

Zip

Legal Description of Property: (Attach if necessary)

Parcel "A" located in the Northeast Quarter (1/4) of the Southwest Quarter (1/4) of Section Thirty-four (34), Township Seventy-four (74) North, Range Twenty-eight (28) West of the 5th P.M., Madison County, Iowa, containing 8.61 acres, as shown in Plat of Survey filed in Book 2003, Page 1786 on March 28, 2003, in the Office of the Recorder of Madison County, Iowa.

1. Wells (check one)

There are no known wells situated on this property.

There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)

There is no known solid waste disposal site on this property.

There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

There is no known hazardous waste on this property.

There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)

There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)

There are no known private burial sites on this property.

There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. Private Sewage Disposal System (check one)

All buildings on this property are served by a public or semi-public sewage disposal system.

This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.

There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.

There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.

There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.

There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]

This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]:

The private sewage disposal system has been installed within the past two years pursuant to permit number _____.

Information required by statements checked above should be provided here or on separate sheets attached hereto:

One (1) inactive well is located approximately 80 yards east of the dwelling unit.

**I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS
FOR THIS FORM AND THAT THE INFORMATION STATED
ABOVE IS TRUE AND CORRECT.**

Signature: Perry D. Borntrager Telephone No.: (515) 705-9036
Perry D. Borntrager, Transferor



Time of Transfer Inspection Report (DNR Form 542-0191)

Property information

Current owner Perry P Sarah Borntvager
Buyer Andrew Herschberger Realtor By Owner (705-9036)
Mailing address 2909 Homestead ave LORIMAR, IA 50149
Site Address/County 1934 330th st / MADISON CO
Legal Description AS ABTRACT

No. of bedrooms 7 Last occupied? June 1, 2001 Records available Yes

Permit/installation date 10-3-04 Separation distances ok/no? ok

Septic system information

Septic tank(s): size 1500 gal material POLY TANK condition ok
Tank pumped? Yes date 6-22-21 licensed pumper Countryside Septic
Septic/trash/processing tank: size material condition
Tank pumped? date licensed pumper

Aerobic treatment unit (ATU) mfg size
Tank pumped? date licensed pumper
Maintenance contract? expiration date service provider
Condition

Pump tanks/vaults: type PRESSURE size 500 gal condition ok

Distribution system: distribution box Yes outlets used 7 condition ok
Header pipe(s) # of lines Pressure dosed?

Secondary treatment:
length of absorption fields 7 60' determined by County Records
condition of fields ok DRY determined by Prabiraj P. Hydronic
type of trench material Chamber Test

Size of sand filter determined by
Vent pipes above grade? discharge pipe located?
Effluent sample taken? Results

Media filters: type
Maintenance contract? expiration date service provider
Condition

NPDES General Permit No. 4: required? permitted? NOI provided



Time of Transfer Inspection Report

Other components:

Alarms NO Working? - disinfection NO working? -

Control box - Timers - inspection ports -

Other components NONE

Overall condition of the private sewage disposal system

Report system status See ATTACHED PAGES

Explain (attach additional pages as needed): _____

Comments: House Has no Full Basement
Has been lived in daily up until June 1, 2021

Site status at conclusion of Time of Transfer inspection:

- Verify that controls are set on the appropriate mode.
- Power is on to all components.
- Revisit all components to verify lids are secure.
- Gather all tools for removal from the site.
- Verify that no sewage is on the ground surface.

Using this worksheet, write a narrative report of the inspection results and attach a site sketch.

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified inspector: [Signature] Date: 6-22-21
 Name (print): Brian Kinabo Certificate #: 9805
 Address: P.O. Box 204 NORWALK, IA 50211
 Phone #: 702-4897

Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office, and to:

Iowa DNR
 Private Sewage Disposal Program
 502 E. 9th St.
 Des Moines, IA 50319

Time of Transfer Report System Status

Address: 1934 330th ST

Date: 6-22-21

Comments: LORIMOR TO 50149

Technician: Brian Rinard

All wastewater from house goes into
septic system. 1500 gallon poly (2) compartment
septic tank with risers was in good
working condition. 500 gallon concrete pump
p.t. tank with pump was also in working
condition. plastic distribution box with
inlet baffle and spread leveler used was also
in good working condition. All (7) laterals
flushed by and took water at inspection.

This is not a guarantee.
This certifies that the septic system
was in working condition at time of inspection

DIAGRAM OF SYSTEM

See
County
Record.

Permit # 163-04 Goodenbergen Inspection 12/16/04

