



Document 2021 GW3935

Book 2021 Page 3935 Type 43 001 Pages 13

Date 9/20/2021 Time 12:10:49PM

Rec Amt \$.00

INDX

ANNO

SCAN

LISA SMITH, COUNTY RECORDER
MADISON COUNTY IOWA

CHEK

**REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT
TO BE COMPLETED BY TRANSFEROR**

TRANSFEROR:

Name: Brett W. Fuller and Katlin M. Fuller
Address: 1865 377th Ave., Brooklyn, IA 52211

TRANSFeree:

Name: Rodney Ferguson and Linda Ferguson
Address: 1147 36th St., Des Moines, IA 50311

Address of Property Transferred:

1410 Walnut Lane, Cumming, Iowa 50061

Legal Description of Property: (Attach if necessary)

Lot Eight (8) of Evans Rural Estates Sub-District, being a part of the Northeast Quarter (1/4) of Section Twenty-five (25), Township Seventy-seven (77) North, Range Twenty-six (26) West of the 5th P.M., Madison County, Iowa.

1. Wells (check one)

- There are no known wells situated on this property.
- There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)

- There is no known solid waste disposal site on this property.
- There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

- There is no known hazardous waste on this property.
- There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

- There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)

- There are no known private burial sites on this property.
- There is a private burial site on this property. The location(s) of the site(s) and known identifying

FILE WITH RECORDER

DNR form 542-0960 (July 18, 2012)

information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. Private Sewage Disposal System (check one)

- All buildings on this property are served by a public or semi-public sewage disposal system.
- This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
- There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
- There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
- There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
- There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
- This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]: _____.
- The private sewage disposal system has been installed within the past two years pursuant to permit number _____.

Information required by statements checked above should be provided here or on separate sheets attached hereto: BF

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS
FOR THIS FORM AND THAT THE INFORMATION STATED
ABOVE IS TRUE AND CORRECT.

Signature: _____

(Transferor)

Telephone No.: (515) 779-5163

* Well is located 50 yards South of walkout basement.



Time of Transfer Inspection Report

Other components:

Alarms _____ Working? _____ disinfection _____ working? _____

Control box _____ Timers _____ inspection ports _____

Other components _____

Overall condition of the private sewage disposal system

Report system status _____

Explain (attach additional pages as needed): ALL WASTE FROM HOUSE GOES TO SEPTIC TANK. TANK LEVELS ABOVE NORMAL DUE TO PLASTIC PIECE OF FILTER BEING JAMMED IN THE D-BOX PIPE.

Comments: PERFORMED HYDRAULIC LOAD TEST USING APPROX 350 GALLONS OF WATER. 1 OF 3 LATERALS STOPPED TAKING WATER SEPTIC TANK WAS PUMPED RELIEVING SOME OF THE DETERIORATION AROUND OUTLET OF TANK

Site status at conclusion of Time of Transfer inspection:

- Verify that controls are set on the appropriate mode.
- Power is on to all components.
- Revisit all components to verify lids are secure.
- Gather all tools for removal from the site.
- Verify that no sewage is on the ground surface.

Revised 9/15/2021 ;

We were able to remove the broken piece of the old effluent filter that was causing a blockage in the outlet line from the septic tank to the distribution box. We also replaced the effluent filter.

Using this worksheet, write a narrative report of the inspection results and attach a site sketch.

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified inspector: 

Date: 7/13/2021

Name (print): BRYCE BAILEY

Certificate #: 11454

Address: GALLON INC. 2785 NE 46TH AVE DES MOINES, IA 50317

Phone #: 515-262-9174

Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office, and to;

Iowa DNR
Private Sewage Disposal Program
502 E. 9th St.
Des Moines, IA 50319



Time of Transfer Inspection Report

Other components:

Alarms _____ Working? _____ disinfection _____ working? _____

Control box _____ Timers _____ inspection ports _____

Other components _____

Overall condition of the private sewage disposal system

Report system status _____

Explain (attach additional pages as needed): ALL WASTE FROM HOUSE GOES TO SEPTIC TANK. TANK LEVELS ABOVE NORMAL DUE TO PLASTIC PIECE OF FILTER BEING JAMMED IN THE D-BOX PIPE.

Comments: PERFORMED HYDRAULIC LOAD TEST USING APPROX 350 GALLONS OF WATER. 1 OF 3 LATERALS STOPPED TAKING WATER SEPTIC TANK WAS PUMPED RELIEVING SOME OF THE DETERIATION AROUND OUTLET OF TANK

Site status at conclusion of Time of Transfer inspection:


- Verify that controls are set on the appropriate mode.
- Power is on to all components.
- Revisit all components to verify lids are secure.
- Gather all tools for removal from the site.
- Verify that no sewage is on the ground surface.

Revised 9/15/2021 ;

We were able to remove the broken piece of the old effluent filter that was causing a blockage in the outlet line from the septic tank to the distribution box. We also replaced the effluent filter.

Using this worksheet, write a narrative report of the inspection results and attach a site sketch.

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified inspector:  Date: 7/13/2021
 Name (print): BRYCE BAILEY Certificate #: 11454
 Address: GALLON INC. 2785 NE 46TH AVE - DES MOINES, IA 50317
 Phone #: 515-262-9174

Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office, and to;

Iowa DNR
Private Sewage Disposal Program
502 E. 9th St.
Des Moines, IA 50319

PRELIMINARY ONSITE WASTEWATER TREATMENT SITE SPECIFICATIONS AND LAYOUT

