BK: 2021 PG: 4103

Recorded: 10/1/2021 at 2:25:21.0 PM

Pages 7

County Recording Fee: lowa E-Filing Fee: \$0.00

Combined Fee: Revenue Tax:

LISA SMITH RECORDER Madison County, Iowa

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

	TO BE COMPLETED BY TRANSFEROR							
	ANSFEROR:							
Nar	ne_Tammy Christensen							
Add	lress _2055 NW State St Unit 311, Ankeny IA	A 50023						
	Number and Street or RR	City, Town or P.O.	State	Zip				
TR	ANSFEREE:							
	ne Richard Shelley and Emily L Shelley							
Mai	,,							
Add	Iress 2490 Wildrose Court, Saint Charles, I	A 50240						
	Number and Street or RR	City, Town or P.O.	State	Zip				
	lress of Property Transferred:							
2490	Wildrose Lane, Saint Charles, IA 50240 Number and Street or RR	City, Town, or P.O.	State	Zip				
		ony, round of the	Oldio	2.10				
Leo	al Description of Property: (Attach if n	ecessary)						
	attached		 					
			The state of the s					
			···········					
1. \	Wells (check one)							
	There are no known wells situated							
	☑ There is a well or wells situated on	this property. The type(s), loca	ition(s) and legal sta	atus are				
	stated below or set forth on an att	ached separate sheet, as neces	sary.					
	Solid Waste Disposal (check one)							
	🔼 There is no known solid waste dis _l	oosal site on this property.						
	There is a solid waste disposal site	e on this property and informatio	n related thereto is	provided in				
	Attachment #1, attached to this do	ocument.		•				
3.	Hazardous Wastes (check one)							
	There is no known hazardous was	te on this property.						
	There is hazardous waste on this	property and information related	thereto is provided	in				
	Attachment #1, attached to this do	ocument.	•					
4.	Արderground Storage Tanks (check	cone)						
	There are no known underground	storage tanks on this property.	(Note exclusions su	ch as				
	small farm and residential motor for							
	instructions.)		,	,				
	☐ There is an underground storage t	ank on this property. The type(s	s), size(s) and anv k	nown				
	substance(s) contained are listed							

5.		vate Burial Site (check one)						
		There are no known private burial sites on this property. There is a private burial site on this property. The location(s) of the site(s) and known						
		identifying information of the decedent(s) is stated below or on an attached separate sheet, as						
c	Driv	necessary. vate Sewage Disposal System (check one)						
.		All buildings on this property are served by a public or semi-public sewage disposal system. This transaction does not involve the transfer of any building which has or is required by law to						
	have a sewage disposal system. There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modification							
	_	are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.						
	Ц	There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal						
		system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.						
		There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private						
		sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.						
		There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided						
		with this form. [Exemption #9] This property is exempt from the private sewage disposal inspection requirements pursuant to						
	the following exemption [Note: for exemption #9 use prior check box]:							
		The private sewage disposal system has been installed within the past two years pursuant to permit number						
		nation required by statements checked above should be provided here or on separate stated attached hereto:						
		The well is located near the pond.						
								
I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS								
	AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.							
Się	gnat	ure: Telephone No.: (515-468-3003						
		- I want						

Legal Description:

Lot Six (6) of Cunningham Rural Estates Sub-District, Madison County, Iowa, located in the Southwest Quarter (1/4) of the Southwest Quarter (1/4) of Section Fourteen (14) and in the Northwest Quarter (1/4) of the Northwest Quarter (1/4) of Section Twenty-three (23) in Township Seventy-five (75) North, Range Twenty-six (26) West of the 5th P.M., Madison County, Iowa.



Time of Transfer Inspection Report

Property Information		;	•			
Current Owner: Tammy Christensen						
Buyer:	14 (Call of the Call of the Ca		Realtor:			
Mailing Address:			NACOTA NA			
Site Address/County:	2490 Wildrose	e Ct, Saint Charl	es IA/ Madison	County		WHITE TAKES OF THE PARTY OF THE
Legal Description						VINE COLUMN TO THE COLUMN TO T
No. of bedrooms:	3 Last	st occupied: Current		Records available:		yes
Permit/ installation date:	12-1-80	Sep	aration distances	s (ok/no?):	ok	
Septic System Information	#			•		
Septic tank(s): Size:	1000 gal	Material:	Concrete	Condition:	good	
Tank pumped? □ □	N Date:	2-19-19	Licensed pump	er:	Forest Seption	3
Septic/Trash/Processing tar	nk: Size:	N	laterial:	C	ondition:	
Tank pumped? $\square Y \square$	N Date:		Licensed pump	er:		***************************************
Aerobic treatment unit (AT	U) mfgr	***************************************		•	Size	
Tank pumped? $\square Y \square$	N Date:		Licensed pun	nper:		***************************************
Maintenance contract?	DYDN Ē	Expiration date:	при	Service provi	ider:	***************************************
Condition:					Moderatory 1	
Pump tanks/vaults: Type: Size:			Condition:			
Distribution system:	Distribution box	Plastic	Outlets used	6	Condition:	good
Header pipe	e(s): 4"sch	40 No. of	lines: 6	Pressur	e dosed?	no
Secondary Treatment:	and fitting an expensed in record to debit an integral and an expensed in the second s	perconductive remarks the promptions and annual	######################################	***************************************		
Length of absorption fields	: 6x85'		Determined by	y: Cou	nty record	
Condition of fields:	good/dry		Determined by	y: Hy	draulic test	
Type of trench material: rock and pipe						
Size of sand filter:			Determined by:			
Vent pipes above grade? □ Y □ N			Discharge pipe located? □ Y □ N			
Effluent sample taken			Results:			
Media Filters: Type:						
Maintenance contract?			Service provider:			
Condition:						
NPDES General Permit No. 4: Required? □ Y□ N Permitted? □ Y□ N NOI provided:						



Time of Transfer Inspection Report

Other components.							
Alarms: □Y□N	Working:	$\square Y \square N$	Disinfection:	$\square Y \square N$	Working:	\square Y \square N	
Control Box:	Timers:		Inspection Ports:				
Other components:			****	***************************************			
Overall condition of the	private sew	age disposal sys	stem:				
Report system status:	Syste	em was working	properly during the	Inspection			
Explain (attach addition	nal pages as i	needed):	Tank is good. D-	box is good. I	Tydraulic te	st was good.	
Lateral field was dry. A	ll plumbing	goes to the septi	c.			***************************************	
Comments: 1 out	t of the 6 late	erals did not take	e water.				
***************************************				// // // // // // // // // // // // // 		Minima de la companya	
Site status at conclusion	of Time of	Transfer inspect	ion:				
 Verify that controls are set on the appropriate mode. Power is on to all components. Revisit all components to verify lids are secure. Gather all tools for removal from the site. Verify that no sewage is on the ground surface. 							
Using this worksheet, w	rite a narrat	ive report of the	inspection results a	nd attach a site	e sketch.		
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.							
Signature of Certified In	aspector:	Bur Ball	W	Dat	e: 8	3-31-21	
Name (print):	Ben Bedwell	1		Certificate	#: 11	612	
Address: 1500	N B Street,	Indianola IA		mpahayaya.		**************************************	
Phone #: 515-6	681-2053					The state of the s	
Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office and to:							
Iowa DNR							
Private Sewage Disposal Program 502 E 9 th St							
DOMEST OF							

Des Moines IA 50319

Work Order 2/19/2019

R Rogers Septic LLC

401 NE 52nd Ave. Des Moines, IA 50313 Phone: (515)282-0777

E-mall: rlck@rogersseptic.com

Service Information

Dorothy Davenport 2490 Wild Rose Lane St. Charles, IA 50240 Contact: Dorothy Davenport

Phone: (641) 629-1533

E-mail: Rbrockman@lowaRealty.com

Job Name

Davenport, Dorothy - TOT with Pumping

Billing Information Dorothy Davenport 2490 Wild Rose Lane St. Charles, IA 50240

• •	, ,			•	
Job Type TOT	PO #	Invoice #	Scheduled 02/19/2019	Start 12:00 PM	End 5:00 PM
Item D-BOX:D-BOX 2 yr Warranty:D-Box 2yr 6 Hole	Description GOOD: 2 year warranty on Distribution Box installed. Inlet and outlet, incased in to top of existing D-Box let Plastic will not corrode or make strong and last a life	I inlet 6 outlets. Sealed concrete. Max dig depth ss then 2ft. decay, and concrete to	Quantity 0.0000	Rate \$1,310.0000	Amount \$0.00
D-BOX:D-Box 90 Day Warranty:D- Box 90day 6 Hole	Basic: 90 Day warranty or Distribution Box installed,	: New Plastic Septic 1 inlet 6 outlets. Max dig Box less then 2ft. Installed	0.0000	\$1,190.0000	\$0.00
TOT:TOT 1000 gal.	BASIC: Time of Transfer (T Real Estate Sale: Documentation. Includes of Docs provided to: DNR, co agents, (If contact info pro Services. Includes: Inspect inspector, locating, pumpli of a 1000 gallon septic tan	locs required per code. unty, sellers, buyers & ovided). tion by a certified ng, cleaning, and disposal	1.0000	\$625.0000	\$625,00
	Additional Fees that may a Waste disposal greater that disposal fees of \$.15 per greater that disposal fees of \$.15 per greater that disposal fees of \$.15 per greater to the second that the	an 1000 gallons additional gallon. ne lids (Tank & D-Box) to harge. If greater then 12" may apply \$50-\$250. Fee avating. tic system & piping, \$50- I be quoted prior to			

TOT report will follow with in 10 days unless

otherwise agreed upon.

Job Subtotal: Madison County: Total Due:

\$625.00 \$0.00 **\$625.00** 1000 Com.

6-85' LATERPES

₹. ±