

Document 2022 GW2691

Book 2022 Page 2691 Type 43 001 Pages 5 Date 9/12/2022 Time 11:55:58AM Rec Amt \$.00

I NDX ANNO SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY 10WA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

TRANSFEROR:

Name: Steven W. Vasey and Marcia K. Vasey Address: 3186 Overland Trl., Ellston, IA 50074

TRANSFEREE:

Name: Brenda Vodraska

Address: 3163 Walnut Ln., Truro, IA 50257

Address of Property Transferred:

3163 Walnut Lane, Truro, Iowa 50257

Legal Description of Property:

A parcel of land located in the Northeast Quarter (1/4) of the Southwest Quarter (1/4) and in the Northwest Quarter (1/4) of the Southeast Quarter (1/4) all in Section 24, Township 74 North, Range 26 West of the 5th P.M., Madison County, Iowa, more particularly described as follows: Commencing at the Northwest Corner of the NE ¼ of the SW ¼ of Section 24, T74N, R26W of the 5th P.M., Madison County, Iowa; thence along the North line of said NE ¼ of the SW ¼ North 90° 00' 00" East 1008.09 feet; thence, along the centerline of a county road, South 03° 44' 52" West 636.69 feet; thence South 85° 28' 01" East 18.00 feet to the Point of Beginning; thence South 85° 28' 01" East 446.52 feet; thence South 00° 00' 00", 297.01 feet; thence South 90° 00' 00" West 388.68 feet; thence North 09° 38' 22" West 337.06 feet to the Point of Beginning.

1. Wells (check one)

- ☐ There are no known wells situated on this property.
- ☑ There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)

- ☑ There is no known solid waste disposal site on this property.
- ☐ There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

- ☑ There is no known hazardous waste on this property.
- ☐ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

- ☑ There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- ☐ There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)

There are no known private burial sites on this property.

FILE WITH RECORDER

DNR form 542-0960 (July 18, 2012)

_		There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.						
6.		rate Sewage Disposal System (check one)						
		All buildings on this property are served by a public or semi-public sewage disposal system.						
		This transaction does not involve the transfer of any building which has or is required by law to have a						
	ΙZI	sewage disposal system. There is a building served by private sewage disposal system on this property or a building without any lawfu						
	ы	sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form						
	П	when recording. There is a building served by private sewage disposal system on this property. Weather or other temporary						
	u	physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be						
		responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.						
		There is a building served by private sewage disposal system on this property. The buyer has executed a						
binding acknowledgment with the county board of health to install a new private sewage dispos this property within an agreed upon time period. A copy of the binding acknowledgment is provi form.								
	П	There is a building served by private sewage disposal system on this property. The building to which the						
	sewage disposal system is connected will be demolished without being occupied. The buyer has executed binding acknowledgment with the county board of health to demolish the building within an agreed upon ti							
	_	period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]						
	This property is exempt from the private sewage disposal inspection requirements pursuant to the follow exemption [Note: for exemption #9 use prior check box]:							
	exemption [Note: for exemption #9 use prior check box]: The private sewage disposal system has been installed within the past two years pursuant to permit number number to permit number							
he	reto							
1.	Wel	is: One well located under the porch of the house; made of stone; unknown depth; unused.						
		I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS						
	FOR THIS FORM AND THAT THE INFORMATION STATED							
		ABOVE IS TRUE AND CORRECT.						
Si	gnatu	ure: Mensferor) Telephone No.: (515) 468-8666						



Time of Transfer Inspection Report (DNR Form 542-0191)

Property information
Current owner Steve Vasey Buyer Realtor Mailing address 3186 Overhand Trail Ellston, Ia. 5007
Site Address/County 3163 Walnut Lane Truro 50257 Legal Description
No. of bedrooms 3 Last occupied? 54// Records available 465
Permit/installation date 10 - 26-16 Separation distances of no?
Septic system information
Septic tank(s): size 1500 material Concrete condition 9000. Tank pumped? 4es date 6-11-22 licensed pumper # 237 wile gent Septic/trash/processing tank: size material condition Tank pumped? date licensed pumper
Aerobic treatment unit (ATU) mfgr size Tank pumped? date licensed pumper Maintenance contract? expiration date service provider Condition
Pump tanks/vaults: type size condition
Distribution system: distribution box 425 outlets used 3 condition 4000 Header pipe(s) 425 # of lines 3 Pressure dosed?
Secondary treatment: length of absorption fields 30100 determined by Probe Measured condition of fields Good determined by Probe Visual type of trench material 364 Chambers
Size of sand filter determined by Vent pipes above grade? discharge pipe located? Effluent sample taken? Results
Media filters: type service provider Service provider
NPDES General Permit No. 4: required? permitted? NOI provided



Time of Transfer Inspection Report

Other components:		~	
Alarms Working?		disinfection	working?
Control box	Timers	inspection ports_	Quiderna-
Other components			***************************************
Overall condition of the private sew	age disposal system	•	
Report system status DUMP	edout	TANK C	loand Sille
Explain (attach additional pages as a	needed):	. un l	J-bav
was draining	g prop	erly to	the
Comments: Laterale	3, eu	verythi	ing Look
7			•
	are set on the approportion appropriate appropriate are street to verify lids are street appropriate a	riate mode.	e
Using this worksheet, write a narrat	tive report of the insp	pection results and att	ach a site sketch.
This report indicates the condition of the inspection. It does not guarantee	-	-	
Signature of Certified inspector: Name (print): MIKE FIG. Address: 331114011 Phone # S15-360 Provide a copy of this report, the nathe person ordering the inspection,	ARKIZUM ST ZUM 0 -0399 arrative report and sk	etch to the seller/age	Tertificate #: 9450 a 50061 int, buyer/agent or
Iowa DNR Private Sewage Disposal Program 502 E. 9 th St. Des Moines, IA 50319			

Permit #095-16 3/63 Walnut Ln. 10/28/16 48' House Brch North 15^{f+}